

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5601Y**AAD2010-031***Not Authored
61 Sep @ 2250h*

07 OCT 2020

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5601Y

VF1ABL15AUC279405

RENAULT

LATITUDE

06/10/2020

CHINA

30/09/2014

PART

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BRACKET FRT RH (Headlamp Lower)
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE RH
- 1 HEADLAMP RH
- 1 HEADLAMP PANEL FRT RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 TOW COVER FRT

LIST

\$	<i>Bu</i>	747.20	✓
\$	<i>Sn</i>	344.70	X
\$	<i>Sn</i>	394.68	X
\$	<i>Sn</i>	116.47	X
\$	<i>Dir</i>	101.40	✓
\$	<i>Sn</i>	10.70	X
\$	<i>Sn</i>	147.00	X
\$	<i>Sn</i>	207.21	X
\$	<i>mgc m</i>	743.60	✓
\$	<i>n</i>	128.30	X
\$	<i>Bu</i>	437.10	✓
\$	<i>Sn</i>	191.40	X
\$	<i>Sn</i>	60.90	X

TOTAL \$ 3,630.66**10% \$ 363.07****\$ 3,267.59****Special Nett**

- 1SET BUMPER CLIP FRT
- 1 BUMPER BRACKET CLIP FRT
- 1 BUMPER SUPPORT CLIP FRT
- 1SET BUMPER RETAINER CLIP FRT
- 1SET BUMPER GRILLE LOWER CLIP
- 1 BUMPER FOG LAMP GRILLE CLIP
- 1 BUMPER SPOILER CLIP
- 1SET WHEELARCH CLIP FRT

\$	<i>nn</i>	90.00	86% ✓
\$	<i>nn</i>	75.00	} X
\$	<i>nn</i>	10.00	
\$	<i>nn</i>	70.00	
\$	<i>nn</i>	70.00	
\$	<i>nn</i>	65.00	
\$	<i>nn</i>	60.00	
\$	<i>nn</i>	80.00	

TOTAL \$ 520.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5601Y**AAD2010-031****TOTAL PARTS \$ 3,787.59****LABOUR**

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn	380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		1,800.00	400
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	20
To rust-proofing and apply undercoat of the affected areas.	\$		250.00	30
To check steering geometry and computer wheel alignment	\$	u	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	y	170.00	X
To remove and refit battery, electrical wiring, fuse box and relay to enable repair.	\$	u	450.00	X
Putty and spray painting of the affected portion.	\$		1,800.00	440

TOTAL \$ 5,620.00**Over All Total \$ 9,407.59****Repair Days (LUMP SUM)****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: