



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SMD 9581 E
HYUNDAI ELANTRA

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING X nn	1	\$379.00
	2	BOOTLID / DD 1715.30 ✓	1	\$1,891.00
	3	BOOTLID SPOILER / DR 569.38 ✓	1	\$876.00
	4	BOOTLID LOGO (HYUNDAI) / nec 60 ✓	1	\$98.00
	5	BOOTLID EMBLEM (ELANTRA) / nec 60 ✓	1	\$78.00
	6	BOOTLID EMBLEM (S) / nec 40 ✓	1	\$44.00
	7	BOOTLID HANDLE ? / DR 196.20 ✓	1	\$679.00
	8	BOOTLID LOCK SWITCH X nn	1	\$411.00
	9	BOOTLID REVERSE CAMERA ? / Shaded 400 ✓	1	\$1,498.00
	10	BOOTLID CARPLATE LAMP (L+R) ? / DR 160 ✓	2	\$584.00
	11	BOOTLID LAMP (L+R) (RH) / DR (LH) ? / DR 12 ✓	1	\$1,242.00 ✓
	12	BOOTLID INNER TRIM X nn	1	\$673.00
	13	BOOTLID LOCK / BT 132.93 ✓	1	\$864.00
	14	BOOTLID LOCK COVER X nn	1	\$219.00
	15	BOOTLID LOCK CATCH X nn	1	\$178.00
	16	BOOTLID HINGE (L+R) / BT 240.80 ✓	2	\$486.00
	17	BOOTLID STOPPER (L+R) X nn	2	\$104.00
	18	BOOTLID WEATHERSTRIP / TN 225 ✓	1	\$368.00
	19	TAIL LAMP (L+R) (RH) / DR 1752 ✓	2	\$2,640.00
	20	TAIL LAMP PANEL (L+R) (RH) ? / BT 197 ✓	1	\$537
	21	REAR BUMPER / DR 459.40 ✓	1	\$1,419.00
	22	REAR BUMPER RETAINER (L+R) / DR 120 ✓	2	\$484.00
	23	REAR BUMPER REINFORCEMENT BAR ? / BT 294.80 ✓	1	\$976.00
	24	REAR BUMPER BRACKET (L+R) X nn	2	NIL
	25	REAR BUMPER BEAM ? X nn	1	\$640.00
	26	REAR BUMPER SPONGE ? X nn	1	NIL
	27	REAR BUMPER REVERSE SENSOR (L+R) (RH) / DR 200 ✓	1	\$432.00
	28	REAR BUMPER REFLECTOR (L+R) (RH) / CNT 127.60 ✓	1	\$340.00
	29	REAR BUMPER LOWER / CNT 400 ✓	1	\$971.00
	30	REAR BUMPER UNDERCOVER X nn	1	\$1034.00
	31	REAR FENDER (L+R) X R	2	\$3740.00
	32	REAR FENDER INNER TRIM (L+R) X (RH) / TN 247.90 ✓	1	\$743.00
	33	REAR FENDER COWLING (L+R) X nn	2	\$488.00
	34	END PANEL ? / DD 454.60 ✓	1	\$1,179.00
	35	END PANEL TOP GARNISH ? / CRH 148.50 ✓	1	\$597.00
	36	REAR SMART LOCK ANTENNA ? / DR (189.70 & 187.50) 377.20 ✓	2	\$2,140.00
	37	SPAREWHEEL PANEL X nn	1	\$1,649.00
	38	SPAREWHEEL PANEL TOP BOARD ? X nn	1	\$896.00
	39	SPAREWHEEL PANEL TOP BOARD TOP MAT X nn	1	\$379.00
	40	EXHAUST PIPE X nn	1	\$1,740.00

41	EXHAUST GASKET	X nn	1	\$ 370.00	
42	EXHAUST BRACKET (L+R)	X nn	2	\$ 174.00	
43	EXHAUST HEAT SHIELD	X nn	1	\$ 391.00	
	9820.61	P = \$22,112.			
	-20%	-10% = \$19,900.80			
	7856.48				
		SUBTOTAL		\$ -	
		LESS 10%		\$ -	
		PARTS TOTAL		\$ -	
SPECIAL NETT			QTY	PRICE	
1	REAR WINDSCREEN SEALANT		1	\$ 200.00	X nn
2	BOOTLID INNER TRIM CLIPS		10	\$ 100.00	X nn
3	BOOTLID SPOILER SEALANT	nec	1	\$ 150.00	30
4	REAR CARPLATE	NEC	1	\$ 120.00	4
5	REAR CARPLATE FRAME		1	\$ 120.00	3
6	TAIL LAMP CLIPS		4	\$ 80.00	X nn
7	TAIL LAMP PANEL SEALANT	nk	21	\$ 300.00	30
8	REAR BUMPER CLIPS	NEC	10	\$ 100.00	30
9	REAR FENDER SEALANT		2	\$ 600.00	X nn
10	REAR FENDER INNER TRIM CLIPS		20	\$ 200.00	X nn
11	REAR FENDER COWLING CLIPS	nk / 20	20	\$ 200.00	4
12	END PANEL SEALANT	NEC	1	\$ 250.00	30
13	END PANEL TOP GARNISH CLIPS	SN = \$190.	10	\$ 100.00	10
14	SPAREWHEEL PANEL SEALANT	NN	1	\$ 350.00	X nn
		SPECIAL NETT TOTAL		\$ 2,870.00	
LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		1	\$ 3,600.00	800
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	900	1	\$ 3,000.00	800
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$ 800.00	30
4	TO RNR REAR WINDSCREEN	—	1	\$ 400.00	X
5	TO RNR REAR BOOT MECHANISM		1	\$ 400.00	50
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS		1	\$ 1,200.00	50
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.		1	\$ 150.00	30
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS		1	\$ 450.00	X
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		1	\$ 150.00	30
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.		1	\$ 800.00	X
11	TO DO WATER LEAK TEST.		1	\$ 120.00	30
12	TO RNR FUEL TANK TO ASSIST WORK LOAD	L = \$1,920	1	\$ 450.00	X
		TOTAL = \$22,010.80			
		-20% = \$17,600			
		TOTAL		\$ 11,520.00	
		GRAND TOTAL COST		\$ 14,390.00	

Steve (LKK) 9/10/20, 4.00pm

nm PL

5 days

L/S

AL spy

P - 7856.48

N - 190

L - 1920

= 9966.48

L/S - 7973.18

= 7950