

COMFORTDELGRO ENGINEERING PTE LTD

LEK

REPAIR ESTIMATE

DATE: 09/10/20

3P INSURANCE: AIG

MODEL: HYUNDAI IONIQ

SURVEYOR:

VEH NO.: SHD4761U

MVA: LOKE WY

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Front Bumper / BR	1		\$418.30
	Front Bumper Bracket Top LH ?	1		\$35.00
	Front Bumper Bracket LH - BR	1		\$28.00
	Front Bumper Centre Moulding / CUT	1		\$188.00
	Front Bumper Grille LH - CUT	1		\$186.90
	Day Light LH - CUT	1		\$642.50
	Front Bumper Clips - MC	10		\$22.00
	Headlamp LH - CUT	1		\$1,993.65
	Headlamp Support Panel Assy X	1		\$949.30
	Front Fender LH - DD	1		\$490.70
	Front Wheel Hub Cap LH - CUT	1		\$346.40
	Front Fender Shield LH ?	1		\$114.70
	Emblem Blue-Drive LH - MC	1		\$26.60
	Front Door LH - DD	1		\$1,797.20
	Front Door Hinge Upper LH X	1		\$65.76
	Front Door Hinge Lower LH X	1		\$65.76
	Front Door Check LH X	1		\$72.98
	Front Door Outer Handle LH X	1		\$78.00
	Rocker Panel Outer Garnish LH X	1		\$290.00
SPARE PARTS SUB TOTAL				\$7,811.75
LESS 20%				\$1,562.35
DISCOUNTED SPARE PARTS TOTAL				\$6,249.40
	Front Tyre LH / TAI	1		\$216.00 Nett
	Front Fender Advertisement LH - MC	1		\$100.00 Nett
	Front Door Comfort Logo LH - MC	1		\$75.00 Nett
	Front Door Advertisement LH - MC	1		\$100.00 Nett
DISCOUNTED SPARE PARTS & NETT TOTAL				\$6,740.40
	Panel Beating		\$1,000.00	960
	Spray Painting		\$900.00	800
	Remove/Refix Door Assy		\$120.00	50
	Wheel Alignment		\$90.00	60
	Check Wiring		\$50.00	30
LABOUR TOTAL				\$2,160.00

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	ESTIMATE TOTAL			\$8,900.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.				

Steve (LKK) WML Proj L
 9/10/99, 5:00pm
 P/P
 By Ref SM
 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**DELGRO
NEERING**

COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline : 65 6383 6280 Facsimile : 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Road Singapore 609549

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 09.10.2020 15:05

Page : 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305427256

COMFORT TRANSPORTATION PTE LTD
7010045

ER NO. 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R)

(O)

(P)

COUNT CARD NO.

REGN NO. SHD4761U	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 09.10.2020 13:00
YR OF MANU 14.05.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU146228	COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 09.10.2020
NATURE: 3P 09.10.2020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Vehicle No.: SHD4761U

YY

Exit Pass

Vehicle No.: SHD4761U

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard