

Not Authorized
Resurvey After Point

4 day

Page 1 / 2

ESTIMATE

Date : 14/10/2020
To : AIG ASIA PACIFIC INSURANCE PTE. LTD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GZ1097U
Model : NISSAN URVAN

Chassis No : JN1MG4E25Z0713853
Engine No : ZD30018670K
Quotation No. : 119811
Ref. No. :
D.O.A. : 07/10/2020
Policy No. : DMCVSN3077171901
Claim Type : TP CLAIMS - AIG
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		HEADLAMP LH	1	565.00	-30	395.50	395.50
2		FRONT BUMPER	1	862.00	-30	603.40	603.40
3		FRONT BUMPER BRACKET LH	1	50.00	-30	35.00	35.00
4		FRONT BUMPER BRACKET LH	1	50.00	-30	35.00	35.00
5		FOG LAMP LH	1	485.00	-30	339.50	339.50
6		FOG LAMP COVER LH	1	152.00	-30	106.40	106.40
7		CORNER PANEL LH	1	698.00	-30	488.60	488.60
8		FRONT DOOR LH	1	1,467.00	-30	1,026.90	1,026.90
9		FRONT DOOR HINGR UPPER	1	95.00	-30	66.50	66.50
10		FRONT DOOR HINGR LOWER	1	95.00	-30	66.50	66.50
11		SIDE STEP LH	1	397.00	-30	277.90	277.90
PARTS TOTAL :							3,441.20

SPECIAL NETT ITEMS

1 ROC STICKER

1 35.00
PARTS TOTAL : 35.00

LABOUR CHARGES

1 TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS
2 TO CHECK AND RECONNECT ALL NECESSARY WIRING
3 TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC

1800.00
100.00
1400.00

LABOUR TOTAL : 3,300.00
SUB-TOTAL : 6,776.20
GST @ 7% for \$ 6,776.20 474.33
GRAND TOTAL (S\$) : 7,250.53

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: