

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 9-Oct-20

INSURANCE: China Taiping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD 4947 B

CC6/CTI20010930/Dr3

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR BUMPER <i>Cnt</i>	1	\$642.04	\$642.04	✓
REAR BUMPER UNDER COVER <i>HW</i>	1	\$773.64	\$773.64	X
REAR BUMPER SIDE RETAINER <i>HW</i>	1	\$157.78	\$157.78	X
REAR BUMPER CLIPS <i>HW</i>	1	\$30.80	\$30.80	✓
REAR BUMPER SIDE CLIP <i>HW</i>	1	\$35.00	\$35.00	X
RETAINER, REAR BUMPER, UPPER SIDE (LH) <i>HW</i>	1	\$42.98	\$42.98	X
RETAINER, REAR BUMPER, SIDE, LH <i>HW</i>	1	\$132.72	\$132.72	X
REAR BUMPER UNDER SIDE COVER (LH) <i>HW</i>	1	\$324.80	\$324.80	X
ARM SUB-ASSY, REAR BUMPER, LH <i>HW</i>	1	\$195.44	\$195.44	X
TAIL LAMP ASSY (UPPER) G5 <i>2 money crack</i>	1	\$942.90	\$942.90	✓
REAR FENDER, LH <i>Buc</i>	1	\$1,171.38	\$1,171.38	X
REAR FENDER INNER PANEL, LH <i>HW</i>	1	\$1,019.20	\$1,019.20	X
REAR FENDER OUTER PANEL, LH <i>HW Dashed</i>	1	\$680.40	\$680.40	X
REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH <i>HW</i>	1	\$773.22	\$773.22	X
REAR FLOOR PANEL SIDE (LH) <i>HW</i>	1	\$386.68	\$386.68	X
REAR FENDER SIDE PANEL (LH) <i>HW</i>	1	\$231.00	\$231.00	X
REAR FENDER SHIELD (LH) <i>HW torn</i>	1	\$187.88	\$187.88	X
REAR FENDER TRIMBOARD (LH) <i>HW</i>	1	\$1,015.00	\$1,015.00	X
REAR FENDER TOP COVER (BLACK COLOR)(LH) <i>HW</i>	1	\$421.54	\$421.54	X
REAR FENDER AIR DUCT <i>HW</i>	1	\$231.14	\$231.14	X
REAR FLOOR PANEL SIDE (LH) <i>HW</i>	1	\$1,004.64	\$1,004.64	X
REAR CROSSMEMBER UNDER COVER <i>HW</i>	1	\$1,247.54	\$1,247.54	X
REAR DOOR RUBBER SEAL OUTER <i>HW</i>	1	\$361.06	\$361.06	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Buc</i>	1	\$1,761.62	\$1,761.62	✓
REAR DOOR OUTER HANDLE <i>Cnt</i>	1	\$130.20	\$130.20	✓
REAR DOOR TRIMBOARD <i>2 HW</i>	1	\$1,015.00	\$1,015.00	X
REAR DOOR RUBBER SEAL OUTER <i>HW</i>	1	\$361.06	\$361.06	X
REAR TYRE (LH) <i>HW</i>	1	\$302.40	\$302.40	X
REAR TYRE RIM (LH) <i>2 distressed 1570.55</i>	1	\$2,177.00	\$2,177.00	✓
REAR WHEEL HUB CAP (LH) <i>Cnt</i>	1	\$248.78	\$248.78	✓
REAR WHEEL BEARING IN & HUB <i>2 Dist 493.00</i>	1	\$854.28	\$854.28	✓
REAR CROSS MEMBER <i>2 distressed 2200.40</i>	1	\$3,080.56	\$3,080.56	✓
REAR SHOCK ABSORBER <i>2 distressed</i>	1	\$165.62	\$165.62	✓
REAR SHOCK ABSORBER MOUNTING <i>HW</i>	1	\$175.42	\$175.42	X
REAR LOWER ARM <i>2 distressed 497.50</i>	1	\$696.50	\$696.50	✓
REAR UPPER ARM <i>2 distressed 356.80</i>	1	\$499.52	\$499.52	✓
REAR KNUCKLE ARM <i>2 distressed 810.60</i>	1	\$1,134.84	\$1,134.84	✓
REAR COIL SPRING <i>HW</i>	1	\$267.96	\$267.96	X

REAR COIL SPRING MOUNTING HW	1	\$0.00	\$0.00	X
REAR BRAKE ABS SENSOR (WIRE) HW	1	\$110.32	\$110.32	X
REAR STABILIZER BAR HW	1	\$436.10	\$436.10	X
REAR STABILIZER LINK HW	1	\$212.24	\$212.24	X
REAR TRAILING ARM 2 distal	1	\$439.88	\$439.88	2✓
REAR ASSIST ARM 2 distal	1	\$479.08	\$479.08	2✓
		\$0.00	\$0.00	X
		12809.43		
SUB TOTAL			\$26,557.16	
LESS 20% 25%		4607.07	\$5,311.43	
DISCOUNTED TOTAL			\$21,245.73	
REAR DOOR COMFORT & APPS STICKER SN HW	1	\$112.00	\$112.00	✓
SUB TOTAL		112.00	\$112.00	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	700/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	700/-
Wiring Charge	1	\$140.00	\$140.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	HW
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	HW
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	HW
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$4,730.00	
ESTIMATE TOTAL			\$26,087.73	
prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

12/10/2020 @ 1700hrs

Not Authorised

PCA by Part.

ryan

9 days.

LKK Auto

Photo after repair with damaged parts.

7/P 11,609.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "No Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: