

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVE SINGAPORE 564535

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Estimate bill:
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

M / s : **India International Insurance Pte Ltd**
64, Cecil Street,
#04/#05-02 IOB Bldg,
Singapore 049711

Attn : Attention : Motor Claims Department
Tel : Tel : 6347 6100
Fax : Fax : 6225 7743

TT 38 / 20 / TP / WT

Registration No : SLK7534E

Make / model : Toyota Harrier

Mileage :

Date :

09 / 10 / 2020

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHC8113U AND SLK7534E ALONG MARYMOUNT ROAD ON 07 OCTOBER 2020 AT ABOUT 1020 HRS.

1pc	Rear bumper	de		\$	1,469.00	1302.8
1set	Rear bumper parktronic sensor kit	mm		\$	400.00	200(SN)
1pc	Rear bumper lower lip	CRA		\$	465.00	✓
2pcs	Rear bumper reflector	x	(Each \$66.00)	\$	132.00	
2pcs	Rear bumper side bracket (Long)	de	(Each \$90.00)	\$	180.00	130
1pc	Rear bumper sponge	7	✓ CRA	\$	150.00	106.3
	Sub A total :			\$	2,796.00	2004.1
	Less 10% discount :			\$	279.60	
	A total :			\$	2,516.40	1503.07

Remove and transfer rear bumper necessary attachment spare part items.

Remove and refit rear bumper, rear bumper parktronic sensor kit, rear bumper lower lip, rear bumper reflector, rear bumper side bracket (Long), rear bumper sponge.

\$ 200 600.00

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.

Tuff koff rear damaged portion.

\$ MNX 150.00

Diagnostic rear parktronic sensor fault error by HHT

\$ 40 180.00

Putty / primer application, spray painting rear boot, rear end panel, rear bumper.

\$ 500 1,200.00

Grand amount :

\$ 4,646.40

2443.07

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

3 Days .

put my part .

before part 7 photos .

Gmc Qiang - 8258082

07/10/2020