

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0738/2020/NS
DATE	:	6-Oct-20
WIP	:	51972

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS ANG KIM CHOO
ADDRESS	:	BLK 50 HOY FATT ROAD #04-119 SINGAPORE 150050
TELEPHONE	:	HP +65 90921348
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800108959-02
VEHICLE NO	:	SLN 3551 R
MODEL CODE	:	AUDI Q2 1.4 TFSI COD TR
MODEL YEAR	:	11/9/2018
ENGINE NO	:	CZE 671923
CHASSIS NO	:	WAUZZZGA9JA089964
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	3-Oct-20
PLACE OF ACCIDENT	:	AROUND QUEEN ST ROAD PARALLEL PARKING

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 3551 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,000.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	\$ 1,100.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,972.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 3551 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Reform d</i>	\$	1,854.00 ✓	1482
2 FRONT BUMPER FIXING PARTS <i>Reform</i>	\$	343.00 +	
3 FRONT BUMPER GRILLE - CENTRE <i>Reform</i>	\$	195.00 +	
4 FRONT BUMPER AIR GUIDE GRILLE - LH <i>Reform</i>	\$	167.00 ✓	133.60
5 FRONT BUMPER END CAP - LH <i>Reform</i>	\$	34.00 ✗	
6 FRONTBUMPER SPOILER <i>Reform</i>	\$	296.00 ✓	236.40
7 FRONT BUMPER CLOSING ELEMENT <i>Reform</i>	\$	154.00 +	
8 WHEEL SPOILER - LH <i>Reform</i>	\$	34.00 +	
9 FRONT BUMPER ADAPTER - LH <i>Reform</i>	\$	35.00 +	
10 RADIATOR GRILLE <i>Reform</i>	\$	1,395.00 +	
11 RADIATOR GRILLE STRIKER PLATE <i>Reform</i>	\$	123.00 +	
12 FRONT BUMPER CARRIER <i>Reform</i>	\$	679.00 +	
13 FRONT BUMPER FOAM FILLER PIECE <i>Reform</i>	\$	77.00 +	
14 FRONT BUMPER TOP COVER <i>Reform</i>	\$	99.00 +	
15 FRONT BUMPER GUIDE SECTION - LH <i>Reform</i>	\$	35.00 +	
16 CAUTION SIGN STICKER <i>Reform</i>	NEC \$	14.00 +	
17 AIRCON STICKER <i>Reform</i>	NEC \$	8.00 +	
18 HEADLIGHT MOUNTING - LH <i>Reform</i>	\$	117.00 +	
19 LED HEADLIGHT - LH <i>Reform</i>	\$	4,859.00 +	
20 LIFT CYLINDER - LH <i>Reform</i>	\$	141.00 +	
SUB TOTAL SPARE PARTS	:	\$ 10,659.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 3551 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT WHEEL COVER - LH / RH <i>New</i>	2	\$	✓ 636.00	+ 508.80
22 FRONT NO PLATE <i>Not New</i>	S/N	\$	X 60.00	
23 SUNDRIES <i>Not New</i>		\$	X 200.00	
TOTAL SPARE PARTS	:	\$	11,555.00	
TOTAL LABOUR CHARGES	:	\$	2,972.00	
GRAND TOTAL	:	\$	14,527.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 09/10/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0738/2020/NS
DATE	:	6-Oct-20
WIP	:	51972

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days ok - 02 Oct 2020 - Garrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS ANG KIM CHOO
ADDRESS	:	BLK 50 HOY FATT ROAD #04-119 SINGAPORE 150050
TELEPHONE	:	HP +65 90921348
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800108959-02
VEHICLE NO	:	SLN 3551 R
MODEL CODE	:	AUDI Q2 1.4 TFSI COD TR
MODEL YEAR	:	11/9/2018
ENGINE NO	:	CZE 671923
CHASSIS NO	:	WAUZZZGA9JA089964
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	3-Oct-20
PLACE OF ACCIDENT	:	AROUND QUEEN ST ROAD PARALLEL PARKING

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 3551 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	\$ 280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,000.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER.	\$ 1,100.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,972.00	\$ 1,522.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 3551 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER	\$	1,854.00	\$ 1,482.00
2 FRONT BUMPER FIXING PARTS	\$	343.00	
3 FRONT BUMPER GRILLE - CENTRE	\$	195.00	
4 FRONT BUMPER AIR GUIDE GRILLE - LH	\$	167.00	\$ 133.60
5 FRONT BUMPER END CAP - LH	\$	34.00	
6 FRONTBUMPER SPOILER	\$	296.00	\$ 236.40
7 FRONT BUMPER CLOSING ELEMENT	\$	154.00	
8 WHEEL SPOILER - LH	\$	34.00	
9 FRONT BUMPER ADAPTER - LH	\$	35.00	
10 RADIATOR GRILLE	\$	1,395.00	
11 RADIATOR GRILLE STRIKER PLATE	\$	123.00	
12 FRONT BUMPER CARRIER	\$	679.00	
13 FRONT BUMPER FOAM FILLER PIECE	\$	77.00	
14 FRONT BUMPER TOP COVER	\$	99.00	
15 FRONT BUMPER GUIDE SECTION - LH	\$	35.00	
16 CAUTION SIGN STICKER	NEC \$	14.00	
17 AIRCON STICKER	NEC \$	8.00	
18 HEADLIGHT MOUNTING - LH	\$	117.00	
19 LED HEADLIGHT - LH	\$	4,859.00	
20 LIFT CYLINDER - LH	\$	141.00	
SUB TOTAL SPARE PARTS	:	\$ 10,659.00	\$ 1,852.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 3551 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
	c/f		\$	1,852.00
21 FRONT WHEEL COVER - LH / RH	2	\$	636.00	\$ 508.80
22 FRONT NO PLATE	S/N	\$	60.00	
23 SUNDRIES		\$	200.00	
TOTAL SPARE PARTS	:	\$	11,555.00	\$ 2,360.80
TOTAL LABOUR CHARGES	:	\$	2,972.00	\$ 1,522.00
GRAND TOTAL	:	\$	14,527.00	\$ 3,882.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.