

CC3/Alh 20010961 / Af d3

Estimated Cost
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle Ho
 at Workshop m/s
 of
 Insured
 Policy No 1806108259
 Claims No 697857375886
 am Insured Excess 800
 (Client's Record)
 Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report

GIA / PR Seen

Est. Repairs

Lum. am

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

DD Alh

MV 105.K
 PV 79.5K
 Nett 55.5K

Date/Time File Postion

1)

Date/Time File Postion

2)

Date/Time File Postion

☐ : Prel. Report
☐ : Final Report

3882.80

SLN355IR 2018/Sept.
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make Audi Q2
 Colour Gray
 Sp Reading 26374
 A/C Insured / Std / NI / NA
 T/Radio Insured / Std / NI / NA

Eng/Ho
 C/No WAUZZ2G AJA089964

Gen. Cond: Good / Fair / Poor / Burnt
 Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or
 Mod Nil / S/Rim / STD A/Rim or

Tyre Size F: 215/60R16
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front
 R/Bal 06 mm
 L/Bal 06 mm

Rear
 R/Bal 06 mm
 L/Bal 06 mm

D.O.A.
 Survey held at Premium
 D.O.I. 09/10/20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front x/s.

The U/C / Chassis frame / Body Structure affected due to collision

Cost of repair 3882.80, 3 days
 (Red: 10644.20 : 73%)

Days Of Repair: 3
 Resurvey No. of Trip:

Site Insp 15
 Interview 15
 Photo 15
 Survey Fee
 Transportation