

REPAIR DETAILS

LCLL

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Oct 2020)

Parts: 143

TOYOTA VIOS 1.5 E (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SLV9367A/12/10/2020 11:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BOOT	25.00	0.00	bb 832.86 FL
2	1	NA	*REAR BOOT HINGE RH	25.00	0.00	bt 69.09 FL
3	1	NA	*REAR BOOT HINGE LH	25.00	0.00	bt 69.09 FL
4	1	NA	*REAR BOOT LOCK ASSY	25.00	0.00	mx 419.48 FL
5	1	NA	*REAR BOOT CATCH	25.00	0.00	mx 40.32 FL
6	1	NA	*REAR BOOT RUBBER	25.00	0.00	mx 184.59 FL
7	1	NA	*BOOT EMBLEM VIOS	25.00	0.00	mx 47.88 FL
8	1	NA	*BOOT EMBLEM E	25.00	0.00	mx 37.28 FL
9	1	NA	*REAR BOOT LOGO	25.00	0.00	mx 53.24 FL
10	1	NA	*BOOT REFLECTOR LAMP RH	25.00	0.00	mx 258.09 FL
11	1	NA	*BOOT REFLECTOR LAMP LH	25.00	0.00	mx 258.09 FL
12	1	NA	*TAILLAMP RH	25.00	0.00	mx 399.84 FL
13	1	NA	*TAILLAMP LH	25.00	0.00	mx 399.84 FL
14	1	NA	*REAR FENDER LH	25.00	0.00	mx 952.88 FL
15	1	NA	*REAR LH MUGGUARD GARNISH	25.00	0.00	mx 83.16 FL
16	1	NA	*REAR BUMPER	25.00	0.00	de 547.05 FL
17	1	NA	*REAR BUMPER RETAINER RH	25.00	0.00	de 162.54 FL
18	1	NA	*REAR BUMPER RETAINER LH	25.00	0.00	de 162.54 FL
19	1	NA	*REAR BUMPER REFLECTOR LAMP RH	25.00	0.00	mx 98.60 FL
20	1	NA	*REAR BUMPER REFLECTOR LAMP LH	25.00	0.00	mx 98.60 FL
21	1	NA	*REAR REINFORCEMENT	25.00	0.00	mx 349.34 FL
22	1	NA	*ENFPANEL	25.00	0.00	Rp 779.42 FL
23	1	NA	*ENDPANEL TOP GARNISH	25.00	0.00	mx 292.22 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

6,596.04

- List Item Discount on L Items (\$\$)

1,649.01

Total Parts (\$\$)

4,947.03

Cheng Auto Bodyworks/SLV9367A/12/10/2020 11:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2915.34

2186.50

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	ENDPANEL SEALANT	nm x	100.00
2	1	PARKING SENSOR	200nm ✓	250.00
3	1	REAR BUMPER CLIPS	30nm ✓	100.00
4	1	REAR FENDER SEALANT	ny x	200.00
5	1	REAR NUMBER PLATE WITH CASE	bt ✓	40.00

Sub Total (\$\$) 690.00

270

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	LABOUR	New 800	2,000.00
2	SPRAYPAINTING	New 800	1,800.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New 30	100.00
4	LOWER PETROL TANK TO FACILITATE REPAIR OF THE REAR FENDER	New x	400.00
5	DISMANTLE AND TRANSFER BOOT FITTINGS AND MECHANISM TO NEW BOOT/FACILITATE REPAIR	New 60	100.00
6	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS	New 60	300.00
7	REMOVE AND REPLACE BUMPER SENSORS & TEST	New 30	150.00

Gross Labour Cost (\$\$) 4,850.00

Cheng Auto Bodyworks/SLV9367A/12/10/2020 11:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1780.

Taufik 17495749
'WP'

Lumpsum Resurvey after repair
5 days

Taufik @ khando.com.

12/10/20 @ 430pm.

2186.50

270

1780

4236.50.

1/583400.

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company