



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838
For 24-hours Roadside Assistance, Call 98203838

Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT20003273	Page	1
	3 ANSON ROAD #16-00	Date	: 9. Oct 2020		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SCJ1928D	Engine No	: L15Z11414235		
Chassis No	: MRHGM660EP000125	Date Time	: 9. Oct 2020 3:29:51 PM		
Model	: CITY 1.5SV CVT 2014 (EURO 4)	Surveyor Name	:		
Owner's Name	: TEY MUI LEE @ TAY MUI LEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 8/10/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAY MUI LEE						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 08/10/2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: CHINA TAIPING						
	TP VEH: SKZ2324K						
71501-T9A-T00ZZ	FACERR.BUMPER <i>de 7 x su</i>	1	463.70	5	440.51	30.84	471.35
33505-T9A-T01	REFLECTOR ASSY.RR. <i>7 x su</i>	1	16.60	5	15.77	1.10	16.87
33555-T9A-T01	REFLECTOR ASSYL.RR. <i>x su</i>	1	16.60	5	15.77	1.10	16.87
71593-T9A-J00	SPACER R.RR.BUMPER SIDE <i>7 x su</i>	1	11.50	5	10.92	0.76	11.68
71598-T9A-J00	SPACER L.RR.BUMPER SIDE <i>x su</i>	1	11.50	5	10.92	0.76	11.68
91505-TM8-003	CLIP.BUMPER <i>7 x su</i>	4	2.30	5	8.74	0.61	9.35
66100-T9A-T50ZZ	PANEL COMPRR. <i>7 x su</i>	1	364.50	5	346.27	24.24	370.51
84640-T9A-T01ZA	LINING ASSYRR.PANEL <i>x su 7 x su</i>	1	66.60	5	63.27	4.43	67.70
33550-T9A-T01	TAILLIGHT ASSYR. <i>R 7 x su</i>	1	205.70	5	195.41	13.68	209.09
04636-T9A-T00ZZ	PANEL SETR.RR.OUTSIDE <i>repair</i>	1	1276.90	5	1213.05	84.91	1297.96
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>7 x su</i>	1	320.00		320.00	22.40	342.40
	Sum Item				2640.63	184.83	2,825.46
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	3250.00 <i>1300</i>		3250.00	227.50	3477.50
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	2080.00 <i>1560</i>		2080.00	145.60	2225.60

Printed on 9/10/2020 3:48:28 PM

This is a computer generated invoice. No signature is required.


Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



+65 6841 3838

For 24-hours Roadside Assistance, Call 98203838
Website: www.98203838.com

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	:	CHINA TAPING INSURANCE (SPORE) PTE
	:	3 ANSON ROAD #16-00
	:	SPRINGLEAF TOWER
	:	SINGAPORE 079909
Registration No	:	SCJ1928D
Chassis No	:	MRHGM6660EP000125
Model	:	CITY 1.5SV CVT 2014 (EURO 4)
Owner's Name	:	TEY MUI LEE @ TAY MUI LEE
Ins Policy No.	:	
Date of Accident	:	8/10/2020

Document No. : SQT20003273
Date : 9. Oct 2020
Customer No. : WZC008
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15Z11414235
Date | Time : 9. Oct 2020 3:29:51 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Survey By	Ratan - 1690010018		
Date & Time	19/10/2020 @ 11:11		
Excess	5 days		
Status	7		
	Total Amount	8,630.63	604.13
	Total (Inclusive of GST)	8667.00	9,234.76

her

Reay before print

Reay before print

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

is subject to final approval from Insurance Company

Signature:

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00. However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded