



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	KCV08661/Mr Tan Su Wai
MOTOR CLAIM DEPT		Reg No/Reg Date	SMA7829X / 20/06/201
78 SHENTON WAY #08-16		Date In/Mileage	/ 74387
AIG BUILDING		Chassis No	GF7W0401722
SINGAPORE 079120		Engine No	4J11YC2390
Contact No 6419 1892		Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
		Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355
Description of Goods / Services					
E PNT88000		RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR			1800 2250.00
E PNT88000		REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK			9 plus 100.00
A 55900099		TOP UP AIR CON GAS AND CHECK A/CON SYSTEM			? 80.00
E PNT98000		PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT-BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, LH FRONT DOOR, RH FRONT DOOR AND AFFECTED PORTION			2450 2800.00
M SUNDRY		APPLY BODY SEALANT			40 120.00
A 54900099		CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			30.00
M SUNDRY		SUPPLY FRONT NUMBER PLATE WITH FRAME			50.00
M SUNDRY		PERFORM RUST PREVENTION			40 80.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			120.00
M SUNDRY		RE-APPLY ZERTONA PAINT PROTECTION (INVOICE)			? 480.00
M SUNDRY		SUNDRIES			20 50.00
M PNL, HEADLAMP SUPT, UPR RH					1.00 58.00 23.00
M PNL, HEADLAMP SUPPORT, UPR					1.00 182.00 23.00
M PNL, HEADLAMP SUPT, UPR LH					1.00 58.00 23.00
M PNL, HEADLAMP SUPT, UPR LH					1.00 58.00 23.00
M PNL, HEADLAMP SUPPORT, LWR					1.00 146.00 23.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



MITSUBISHI MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-85001111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	KCV08661/Mr Tan Su Wai
MOTOR CLAIM DEPT		Reg No/Reg Date	SMA7829X / 20/06/201
78 SHENTON WAY #08-16		Date In/Mileage	/ 74387
AIG BUILDING		Chassis No	GF7W0401722
SINGAPORE 079120		Engine No	4J11YC2390
Contact No 6419 1892		Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
		Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355	
Description of Goods / Services						
M	PANEL, HEADLAMP SUPPORT, LMR	? XSVL		1.00	155.00 23.00	119.35
M	CONDENSER ASSY, A/C REFRIG	? bt		1.00	857.00 23.00	659.89
M	RADIATOR ASSY	? bt		1.00	1091.00 23.00	840.07
M	TANK ASSY, RADIATOR COND	X SVL		1.00	103.00 23.00	79.31
M	FAN, COOLING, LH	? XSVL		1.00	78.00 23.00	60.06
M	FAN, COOLING, LH	? XSVL		1.00	78.00 23.00	60.06
M	SHROUD, COOLING FAN	? XSVL		1.00	258.00 23.00	198.66
M	MOTOR, COOLING FAN, LH(120W)	? XSVL		1.00	479.00 23.00	368.83
M	MOTOR, COOLING FAN, LH(120W)	? XSVL		1.00	479.00 23.00	368.83
M	LLC 4L	new		1.00	26.00 23.00	20.02
M	BRACKET, RADIATOR GRILLE, RH	? XSVL		1.00	17.00 23.00	13.09
M	BRACKET, RADIATOR GRILLE, LH	? XSVL		1.00	13.00 23.00	10.01
M	HOOD	54		1.00	975.00 23.00	750.75
M	HINGE, HOOD, LH	? XSVL		1.00	68.00 23.00	52.36
M	HINGE, HOOD, RH	? XSVL		1.00	68.00 23.00	52.36
M	INSULATOR, HOOD	de		1.00	133.00 23.00	102.41
M	WEATHERSTRIP, HOOD	new		1.00	40.00 23.00	30.80
M	LATCH, HOOD	54		1.00	76.00 23.00	58.52
M	FENDER, FR LH	new		1.00	688.00 23.00	529.76
M	FENDER, FR RH	new		1.00	688.00 23.00	529.76
M	MOULDING, FR BUMPER, LH	? XSVL		1.00	116.00 23.00	89.32
M	MOULDING, FR BUMPER, RH	? XSVL		1.00	116.00 23.00	89.32
M	MOULDING, FR WHEEL ARCH, LH	? new		1.00	199.00 23.00	153.23
M	MOULDING, FR WHEEL ARCH, RH	? new		1.00	199.00 23.00	153.23
M	HEADLAMP ASSY, LH	new		1.00	2125.00 23.00	1636.25
M	HEADLAMP ASSY, RH	new		1.00	2125.00 23.00	1636.25
M	LAMP ASSY, FOG, FR LH	? XSVL		1.00	348.00 23.00	267.96
M	LAMP ASSY, FOG, FR RH	? XSVL		1.00	348.00 23.00	267.96
M	BRACKET, FR BUMPER SIDE, LH	? XSVL		1.00	18.00 23.00	13.86
M	BRACKET, FR BUMPER SIDE, RH	? XSVL		1.00	18.00 23.00	13.86
M	FACE, FR BUMPER	new		1.00	859.00 23.00	661.43
M	EXTENSION, FR BUMPER	de		1.00	426.00 23.00	328.02
M	GARNISH, FR BUMPER, LH	? de		1.00	75.00 23.00	57.75

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	KCV08661/Mr Tan Su Wai
MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Reg No/Reg Date	SMA7829X / 20/06/201
		Date In/Mileage	/ 74387
		Chassis No	GF7W0401722
		Engine No	4J11YC2390
		Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
		Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	10/10/2020/ 12:48	BLE	247 / DonBong	58355		
Description of Goods / Services							
M	GARNISH,FR BUMPER,RH	? XSVL		Qty	Unit Price	Disc%	Amount
M	COVER,FR BUMPER CA	? XSVL		1.00	75.00	23.00	57.75
M	GARNISH,FR BUMPER SIDE	? XSVL		1.00	294.00	23.00	226.38
M	GARNISH,FR BUMPER SIDE	? XSVL		1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE CA			1.00	48.00	23.00	36.96
M	GARNISH,FR BUMPER SIDE CA			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE CA			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE CA			1.00	112.00	23.00	86.24
M	GARNISH,FR BUMPER SIDE CA			1.00	112.00	23.00	86.24
M	REINF,FR BUMPER SIDE,RH	? bt		1.00	69.00	23.00	53.13
M	REINFORCEMENT,FR BMRP SIDE	XSVL		2.00	22.00	23.00	33.88
M	REINF,FR BUMPER SIDE,LH	? bt		1.00	60.00	23.00	46.20
M	REINFORCEMENT,FR BUMPER	? bt		1.00	134.00	23.00	103.18
M	BAR,FR BUMPER GUARD	? XSVL		1.00	130.00	23.00	100.10
M	BAR,FR BUMPER GUARD	? XSVL		1.00	130.00	23.00	100.10
M	REINFORCEMENT,FR BUMPER	? bt		1.00	503.00	23.00	387.31

Estimate

SURVEYOR NAME: Rasul-ly 90010068
 SURVEYOR SIGNATURE: [Signature]
 DATE: 12/10/2020 @ 1430
 REMARKS: 8 days
EXCESS: THA / PEVER
Repair before paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by	7% GST on	18513.11	Nett	18,513.11
				1295.92
Authorized signatory and company stamp			Total Payable	19,809.03

19,407.08

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.