



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT20003293	Page	1
Registration No	: SLZ6073X	Date	: 12. Oct 2020		
Chassis No	: JHMGK5850JX205995	Customer No.	: WZL009		
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	Svc Advisor	: NG SIN HAI		
Owner's Name	: TAN JIN HE, CORNELIUS BERTRAND	Engine No	: L15B33113153		
Ins Policy No.	:	Date Time	: 12. Oct 2020 12:27:56 PM		
Date of Accident	: 11/10/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-T5B-J50ZZ	FACE,RR.BUMPER <i>de</i>	1	515.50	25	386.62	27.06	413.68
71502-T5A-J60	COVER,R.RR.BUMPER <i>?</i>	1	21.20	25	15.90	1.11	17.01
71507-T5A-J60	COVER,L.RR.BUMPER <i>scr</i>	1	21.20	25	15.90	1.11	17.01
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR <i>de</i>	1	212.10	25	159.07	11.13	170.20
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER <i>re</i>	9	2.30	25	15.52	1.09	16.61
68100-T5B-Z50ZZ	TAILGATE COMP <i>bu</i>	1	749.60	25	562.20	39.35	601.55
74440-T5A-003	WEATHERSTRIPTAILGATE <i>re</i>	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE <i>jam</i>	1	86.20	25	64.65	4.53	69.18
75722-T5L-T01	EMBLEMRR. <i>re</i>	1	11.90	25	8.92	0.62	9.54
74890-T5B-911	GARNISH ASSY,RR.LICENSE <i>scr</i>	1	219.10	25	164.32	11.50	175.82
75701-T5A-000	EMBLEMH <i>re</i>	1	10.70	25	8.02	0.56	8.58
66100-TAR-T10ZZ	PANEL COMPRR. <i>bu</i>	1	328.60	25	246.45	17.25	263.70
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>bu</i>	1	701.00	25	525.75	36.80	562.55
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE <i>repair</i>	1	585.30	25	438.97	30.73	469.70
33500-T5A-J02	TAILLIGHT ASSY,R. <i>scr</i>	1	244.60	25	183.45	12.84	196.29
33550-T5A-J02	TAILLIGHT ASSYL. <i>scr</i>	1	244.60	25	183.45	12.84	196.29
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER <i>re</i>	1	11.70	25	8.77	0.61	9.38

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLZ6073X
Chassis No : JHMGK5850JX205995
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : TAN JIN HE, CORNELIUS BERTRAND
Ins Policy No. :
Date of Accident : 11/10/2020

Document No. : SQT20003293 Page 2
Date : 12. Oct 2020
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15B33113153
Date | Time : 12. Oct 2020 12:27:56 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>new</i>	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>new</i>	1	60.00		60.00	4.20	64.20
NMRS-4P	4 PCS REAR SENSOR <i>new</i>	1	149.20	10	134.28	9.40	143.68
74940-SZW-003	BUZZER ASSYSMART ?	1	62.90	25	47.17	3.30	50.47
Sum Item					3341.74	233.91	3,575.65
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00 <i>✓</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00 <i>✓</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00 <i>✓</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 <i>✓</i>		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 <i>✓</i>		180.00	12.60	192.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00 <i>580</i>		650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00 <i>580</i>		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS (N)	1	650.00 <i>✓</i>		650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00 <i>325</i>		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 <i>✓</i>		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N) <i>-L</i>	1	650.00 <i>✓</i>		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	8000.00 <i>5200</i>		8000.00	560.00	8560.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00 <i>3120</i>		4000.00	280.00	4280.00
Bo-Tow	TOWING SERVICE receipt ?	1	120 <i>✓</i>		120	58.40	178.40
Sum Labor					16110.00	1,127.70	17,237.70

Survey By Rahul - Up 901008
Date & Time 13/10/2020 @ 1120
Excess _____

Total Amount 19,451.74 1,361.61 20,813.35
Total (Inclusive of GST) 20,813.35

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg


For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLZ6073X
Chassis No : JHMGK5850JX205995
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : TAN JIN HE, CORNELIUS BERTRAND
Ins Policy No. :
Date of Accident : 11/10/2020

Document No. : SQT20003293 Page 3
Date : 12. Oct 2020
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15B33113153
Date | Time : 12. Oct 2020 12:27:56 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status	12 days						
Signature							

Rep before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.