

HONDA**KAH MOTOR CO. SDN. BHD.**

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 300 BEACH ROAD #17-04/07
 THE CONCOURSE
 SINGAPORE 199555

Registration No : SLZ6073X

Chassis No : JHMGK5850JX205995

Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)

Owner's Name : TAN JIN HE, CORNELIUS BERTRAND

Ins Policy No. :

Date of Accident : 11/10/2020

Document No. : SQT20003293

Date : 12. Oct 2020

Customer No. : WZL009

Svc Advisor : NG SIN HAI

Engine No : L15B33113153

Date | Time : 12. Oct 2020 12:27:56 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
04715-T5B-J50ZZ	FACE,RR.BUMPER <i>de</i>	1	515.50	25	386.62	27.06	413.68
71502-T5A-J60	COVER,R.RR.BUMPER <i>? Xsvc</i>	1	21.20	25	15.90	1.11	17.01
71507-T5A-J60	COVER,L.RR.BUMPER <i>scr</i>	1	21.20	25	15.90	1.11	17.01
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR <i>de</i>	1	212.10	25	159.07	11.13	170.20
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER <i>re</i>	9	2.30	25	15.52	1.09	16.61
68100-T5B-Z50ZZ	TAILGATE COMP <i>buc</i>	1	749.60	25	562.20	39.35	601.55
74440-T5A-003	WEATHERSTRIPTAILGATE <i>re</i>	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE <i>jam</i>	1	86.20	25	64.65	4.53	69.18
75722-T5L-T01	EMBLEMRR. <i>re</i>	1	11.90	25	8.92	0.62	9.54
74890-T5B-911	GARNISH ASSY,RR.LICENSE <i>scr</i>	1	219.10	25	164.32	11.50	175.82
75701-T5A-000	EMBLEMH <i>re</i>	1	10.70	25	8.02	0.56	8.58
66100-TAR-T10ZZ	PANEL COMPRR. <i>buc</i>	1	328.60	25	246.45	17.25	263.70
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>buc</i>	1	701.00	25	525.75	36.80	562.55
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE <i>requis</i>	1	585.30	25	438.97	30.73	469.70
33500-T5A-J02	TAILLIGHT ASSY,R. <i>scr</i>	1	244.60	25	183.45	12.84	196.29
33550-T5A-J02	TAILLIGHT ASSYL. <i>scr</i>	1	244.60	25	183.45	12.84	196.29
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>re</i>	1	11.70	25	8.77	0.61	9.38

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLZ6073X
Chassis No : JHMGK5850JX205995
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : TAN JIN HE, CORNELIUS BERTRAND
Ins Policy No. :
Date of Accident : 11/10/2020

Document No. : SQT20003293 Page 2
Date : 12. Oct 2020
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15B33113153
Date | Time : 12. Oct 2020 12:27:56 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>neu</i>	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5 <i>neu</i>	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00		60.00	4.20	64.20
NMRS-4P	4 PCS REAR SENSOR <i>neu</i>	1	149.20	10	134.28	9.40	143.68
74940-SZW-003	BUZZER ASSYSMART <i>? cm</i>	1	62.90	25	47.17	3.30	50.47
Sum Item					3341.74	233.91	3,575.65
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	580	650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	580	650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS (N)	1	650.00		650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	325	650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	8000.00	5200	8000.00	560.00	8560.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	3120	4000.00	280.00	4280.00
Bo-TOW	TOWING SERVICE receipt? Xan 1 X 120				120	8.40	
Sum Labor					16110.00	1,127.70	17,237.70

Survey By

Date & Time

Excess

Total Amount 19,451.74 1,361.61 20,813.35

Total (Inclusive of GST) 20,813.35

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

QUOTATION

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLZ6073X
Chassis No : JHMGK5850JX205995
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : TAN JIN HE, CORNELIUS BERTRAND
Ins Policy No. :
Date of Accident : 11/10/2020

Document No. : SQT20003293 Page 3
Date : 12. Oct 2020
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15B33113153
Date | Time : 12. Oct 2020 12:27:56 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Status

Signature

12 days
for
Rey before part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/10/2020 12:54:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.