

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0761/2020/NS
DATE : 12-Oct-20
WIP : 52787

10016.64

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.
YOUR INSURED VEH NO : GBG 3880 X

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LEE KIN HONG THOMAS
ADDRESS : 49 HUME AVENUE
#03-03
SINGAPORE 598749
TELEPHONE : HP +65 97303690
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800143049
VEHICLE NO : SMF 9994 L
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 30/11/2018
ENGINE NO : DAX 030893
CHASSIS NO : WAUZZZF2J2125132
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Oct-20
PLACE OF ACCIDENT : LORONG 8 TOA PAYOH HAWKER CENTRE



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 9994 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00	1000
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 2,700.00	950 Bonnet 550 Arch trim x 02 = 200K = 400
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,672.00	950



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9994 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER	1	\$ 2,595.00	+
2 FRONT BUMPER FIXING PARTS	1	\$ 267.00	+
3 FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 222.00	+
4 FRONT BUMPER GRILLE - CENTRE	1	\$ 142.00	+
5 FRONT SPOILER	1	\$ 754.00	+
6 FRONT BUMPER UNDERRUN BAR	1	\$ 474.00	+
7 FRONT BUMPER CLOSING ELEMENT	1	\$ 171.00	+
8 RADIATOR GRILLE	1	\$ 3,490.00	✓ 2792.00
9 QUATTRO INSCRIPTION	1	\$ 95.00	✓ 75.36
10 RADIATOR GRILLE STRIKER PLATE	1	\$ 241.00	✓ 192.80
11 FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,148.00	+
12 FRONT BUMPER END CAP - LH / RH	2	\$ 182.00	+
13 LOCKING CLIP	4	\$ 15.00	+
14 FRONT PARKING AID SENSOR - INNER	2	\$ 484.00	+
15 FRONT PARKING AID SEAL RING	4	\$ 14.00	+
16 FRONT BUMPER FOAM FILLER PIECE	1	\$ 285.00	+
17 FRONT BUMPER CARRIER	1	\$ 911.00	+
18 FRONT BUMPER TOP COVER	1	\$ 127.00	+
19 AIRCON STICKER	NEC	\$ 20.00	+
20 CAUTION SIGN STICKER	NEC	\$ 14.00	+
SUB TOTAL SPARE PARTS	:	\$ 11,651.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 9994 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 BONNET <i>Dented</i>		\$ 4,012.00 ✓	3209.60
22 BONNET ATTACHMENT PARTS <i>Not u</i>		\$ 139.00 +	
23 BONNET IMPACT PROTECTION - LH } <i>Nec</i>		\$ 28.00 ✓	21.84
24 BONNET IMPACT PROTECTION - RH }		\$ 27.00 ✓	21.52
25 BONNET IMPACT PROTECTION - CENTRE <i>Nec</i>		\$ 27.00 ✓	21.52
26 HEADLIGHT MOUNTING - LH / RH } <i>Not Nec</i>	2	\$ 234.00 +	
27 LED HEADLIGHT - LH / RH }	2	\$ 15,862.00 +	
28 LIFT CYLINDER - LH / RH }	2	\$ 276.00 +	
29 RADIATOR AIR GUIDE - LH / RH }	2	\$ 116.00 +	
30 RADIATOR AIR GUIDE - UPPER }		\$ 48.00 +	
31 RADIATOR AIR GUIDE - CENTRE }		\$ 42.00 +	
32 RADIATOR AIR GUIDE - LOWER }		\$ 48.00 +	
33 FRONT WHEEL COVER - LH / RH <i>Nec</i>	2	\$ 1,250.00 -	1000.00
34 FRONT NO PLATE <i>Best</i>	S/N	\$ 60.00 ✓	
35 SUNDRIES <i>Not Nec</i>		\$ 300.00 X	
TOTAL SPARE PARTS	:	\$ 34,120.00	
TOTAL LABOUR CHARGES	:	\$ 5,672.00	
GRAND TOTAL	:	\$ 39,792.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *13/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

S.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT