

(09/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / SMO 20011003/4yd3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLLS37M

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/10/20 2/5 @ 5400 confirmed with chris

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) __ \$ + RS __ \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER

SINGAPORE 048623

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLL537M

MAKE MODEL : HONDA VEZEL

REFERENCE : 1AP-2020OCT-13

DOA : 09-Oct-20

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER	762.30	1 \$ 1,065.90	Dis ✓
FRONT BUMPER SIDE RETAINER LH	45.50	1 \$ 156.40	✓
FRONT BUMPER LOWER SKIRT	420	1 \$ 650.00	Torn ✓
FRONT BUMPER REINFORCEMENT		1 \$ 458.50	11X ✓
FRONT BUMPER FOGLAMP LH		1 \$ 520.00	11X ✓
FRONT BUMPER FOGLAMP COVER LH		1 \$ 274.00	11X ✓
HEADLAMP LH - LED		1 \$ 1,959.90	CRA ✓
HEADLAMP BRACKET LH		1 \$ 114.60	11X ✓
BONNET		1 \$ 1,207.00	11X ✓
FRONT FENDER LH	466.20	1 \$ 940.60	11X ✓
FRONT FENDER EMBLEM - HYBRID	82.50	1 \$ 205.00	11X ✓
FRONT FENDER INNER SHIELD		1 \$ 238.90	Torn ✓
FRONT WHEEL ARCH GARNISH LH	248.50	1 \$ 414.00	11X ✓
FRONT ROCKER PANEL GARNISH LH		1 \$ 477.10	11X ✓
FRONT SUPPORT PANEL		1 \$ 613.00	11X ✓
FRONT SHOCK ABSORBER LH		1 \$ 498.40	11X ✓
FRONT WHEEL HUB LH		1 \$ 368.00	11X ✓
FRONT WHEEL HUB BEARING LH	245.50	1 \$ 364.00	11X ✓
FRONT KNUCKLE ARM LH	Knuckle arm LH	1 \$ 485.00	11X ✓
FRONT LOWER ARM LH	399.50	1 \$ 512.00	11X ✓
FRONT ANTI ROLL BAR LINK LH		1 \$ 258.00	11X ✓

\$ 11,780.30

LESS 20% \$ 2,356.06

SUBTOTAL \$ 9,424.24

BALANCE C/F \$ 9,424.24

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 9,424.24	
FRONT BUMPER CLIPS	1	\$ 50.00	11X ✓
HEADLAMP CLIPS	1	\$ 50.00	11X ✓
FRONT BUMPER SENSOR	1 SET	\$ 250.00	11X ✓
FRONT FENDER INNER SHIELD CLIPS	1	\$ 50.00	11X ✓
FRONT FENDER SEALANT	1	\$ 100.00	11X ✓

ESTIMATION QUOTE

SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE #05-01/06
 SINGAPORE LAND TOWER
 SINGAPORE 048623
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLL537M
MAKE MODEL : HONDA VEZEL
REFERENCE : 1AP-2020OCT-13
DOA : 09-Oct-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT WHEEL ARCH CLIPS	1	\$ 50.00	11X
FRONT RIM LH	1	\$ 1,000.00	cut 600
FRONT TYRE LH	1	\$ 800.00	11X

SUBTOTAL \$ 2,350.00

BALANCE C/F \$ 11,774.24

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 11,774.24

CHECK WIRING AND LIGHTING SYSTEM	1	\$ 100.00	20
WHEEL ALIGNMENT	2	\$ 100.00	60
TO REMOVE AND REFIT UNDERCARRIAGE ITEMS	3	\$ 250.00	120
PANEL BEATING ON AFFECTED AREA	3	\$ 1,500.00	550
SPRAY PAINTING ON AFFECTED AREA	4	\$ 1,000.00	800
APPLY ANTI RUST ON AFFECTED AREA	5	\$ 100.00	30

SUBTOTAL \$ 3,050.00

GRAND TOTAL \$ 14,824.24

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5771-80
 202
 P- 4577-44
 S.N- 700.00
 L- 1580-02
 6857-44
 56P1

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996

Fax : (65) 6384 1996

Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg

Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order:

SLL537M

Date

15.10.20 14:54

Factory Japan 2019.0.1 Copyright (c) 2018 Hunter Engineering : Honda : Vezel Hybrid : RU3

Front : Left

Actual	Before	Specified Range
-2°56'		-1°00' 1°00'
5°39'		4°00' 6°00'
1°14'		-0°08' 0°08'
17°21'		11°30' 13°30'
14°26'		10°30' 14°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°07'		-1°00' 1°00'
6°32'		4°00' 6°00'
0°13'		-0°08' 0°08'
16°04'		11°30' 13°30'
16°11'		10°30' 14°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-3°03'		-0°45' 0°45'
-0°53'		
1°17'		
1°27'		-0°16' 0°16'

Rear : Left

Actual	Before	Specified Range
-1°18'		-2°30' -0°30'
0°21'		0°00' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°39'		-2°30' -0°30'
0°01'		0°00' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°20'		-0°45' 0°45'
0°22'		0°00' 0°31'
0°10'		
0mm		