## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

	CO. REG:200/07/43D GST REG:2007	
9	2 dys, 12/10/20, 300 pm, 1	_/s
ES	IMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6231 A	AL SM
1 pc	End panel × K End panel inner garnish × MM	\$ 250 00 X \$ 74.00 X
1 p	Rear bumper $\sim 00$	\$ 696.00 /
1 p		\$ 206.00 / \$ 58.00 /
2 p	s Rear bumper side bracket o/s & n/s @ \$29.00 / [[K	\$ 114.00 X
1 p	Rear humper inner sponge ! X NM	\$ 607.00 X
1 p	Rear bumper reinforcement 1 × MM	\$ 108.00 X
2 p	Rear bumper stay o/s & n/s @ \$53.00 X M//	s 36.00 ⊀
2 p	L = sleet @ \$18 (M) 3	
2 p	Rear bumper reinforcement upper bracket @ \$18.00 🔨 🗥	\$ 36.00 <del>×</del> \$ 92.00 <del>×</del>
2 p	Rear bumper reflector n/s & o/s @ \$46.00 X MM	\$ 2,277.00
	960	
	$-\frac{10^{7}l_{0}}{10^{11}l_{0}}$ Less 10%	\$ 227.70 \$ 2,049.30
	864	\$ 2,049.30
S/I 1 s 1 s	End panel inner garnish clips   M  Parts prices are subject to committation  Third party survey is on a "Without Prejudice" b  No illegal modification(s) is allowed	100.00 🔍
1 5	is subject to final approval from Insurance Com	ipany p 200.00
1 5	Rear bumper protector INC Acknowledged by Repairer Signature: Date:	50.00 <i>f</i> g
	Sundry  To diamontal / replace reverse sensor to new bumper and $564$	
	reset to the same	\$ 120.00 <i>31</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 20
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the the same	475-29 99 <b>\$</b> 800.00 <i>309</i>
	To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid	\$ 800.00 JOO
	To apply rustproofing on the repaired and replaced panels.	\$ 150.00 <b>4 1 3 4</b> ,687.30
		700