

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: MOTOR CLAIMS DEPARTMENT

ACCIDENT INVOLVING GBK784P [YOUR INSURED] & GBJ5602D [OUR CLIENT]
ON 04/10/2020.

ESTIMATED REPAIR COSTS FOR GBJ5602D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	FRONT BONNET <i>Dent</i>	825.50 \$ 956.62
1PC	FRONT BONNET "TOYOTA" LOGO <i>Ne</i>	\$ 66.15
2PCS	FRONT BONNET HINGE LH & RH @ \$48.85 EACH <i>HL</i>	\$ 97.70
1PC	FRONT BONNET INNER LOCK <i>HL</i>	\$ 182.90
1PC	FRONT BONNET INNER LOCK CABLE <i>HL</i>	\$ 47.80
2PCS	FRONT BONNET INNER RUBBER SEAL @ \$49.20 EACH <i>HL</i>	\$ 98.40
1SET	FRONT BONNET INNER RUBBER SEAL CLIPS <i>HL</i>	\$ 25.00
1PC	FRONT UPPER GRILLE <i>cut</i>	221.70 \$ 388.20
1PC	FRONT CENTRE GRILLE <i>cut</i>	\$ 313.60
1PC	FRONT CENTRE GRILLE RADAR SENSOR ASSY. <i>Dent</i>	\$ 1,299.10
1PC	FRONT LOWER GRILLE <i>HL</i>	\$ 274.60
1SET	FRONT GRILLE CLIPS <i>HL</i>	\$ 35.00
1PC	FRONT SUPPORT PANEL ASSY. <i>HL</i>	\$ 383.00
1PC	FRONT BRACE PANEL <i>HL</i>	\$ 86.70
1PC	FRONT INTERCOOLER <i>HL</i>	2584.30 \$ 1,558.19
2PCS	FRONT HEADLAMP LH & RH @ \$2706.80 <i>cut</i> <i>HL</i>	\$ 5,413.60
1PC	FRONT RADIATOR <i>HL</i>	\$ 2,268.20
1PC	FRONT RADIATOR TANK <i>HL</i>	\$ 399.20
1PC	FRONT AIR-CON CONDENSOR <i>HL</i>	\$ 1,416.00
1PC	FRONT FAN MOTOR <i>HL</i>	\$ 1,409.10
1PC	FRONT FAN MOTOR COWLING ASSY. <i>HL</i>	\$ 366.38
1PC	FRONT BUMPER <i>cut</i>	\$ 548.20
1SET	FRONT BUMPER CLIPS <i>HL</i>	\$ 35.00
2PCS	FRONT BUMPER SIDE RETAINER @ \$28.70 EACH <i>HL</i>	\$ 57.40
1PC	FRONT LH FENDER <i>HL</i>	\$ 175.80
1PC	FRONT LH FENDER MIRROR <i>HL</i>	\$ 230.90

PARTS SUM: \$ 16,719.06

PARTS LESS 25%: \$ 4,179.77

PARTS TOTAL: \$ 12,539.30

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY RADIATOR COOLANT	\$ 80.00	44
*	TO SUPPLY FRONT SUPPORT PANEL SEALANTS	\$ 80.00	44
*	TO DESIGN & PASTE FRONT COMPANY STICKER	\$ 300.00	44
*	TO SUPPLY FRONT NO. PLATE & HOLDER <i>cut 1st</i>	\$ 80.00	45/-
*	TO CHARGE & DISCHARGE AIR-CON GAS	\$ 100.00	44
*	TO REMOVE & REFIT FRONT AIR-CON CONDENSOR & RADIATOR, & TO CONDUCT PRESSURE TEST.	\$ 400.00	44
*	TO REMOVE DAMAGE FRONT INTERCOOLER & CONDUCT TURBO PRESSURE TEST	\$ 300.00	44
*	TO REPLACE DAMAGED FRONT RADAR SENSOR, DIAGNOSE & RESET TO FACTORY DEFAULT SETTINGS	\$ 500.00	180/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,800.00	600/-
*	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	\$ 1,800.00	400/-
*	TO COMPUTERIZED REFOCUS FRONT HEADLAMP BEAM	\$ 120.00	30/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS.	\$ 280.00	44
*	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	\$ 280.00	30/-

LABOUR & S/N TOTAL: \$ 6,120.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 18,659.30

14/10/2020 @ 1600h

Not Andrew

2/5mm 4 days.

[Signature]

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK784P [YOUR INSURED] & GBJ5602D [OUR CLIENT]

ON 04/10/2020.

SUPPLYMENTARY ITEMS FOR GBJ5602D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	FRONT GRILLE BASE <i>monny crack</i>	\$ 419.24
1PC	FRONT REINFORCEMENT BAR LOWER <i>st</i> 357.10	\$ 627.42

PARTS SUM: \$ 1,046.66
PARTS LESS 25%: \$ 261.67
PARTS TOTAL: \$ 785.00

GRAND TOTAL SUPPLEMENTARY ITEMS : \$ 785.00

ryan
2kk Auto
8