

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GAY BANG HOCK
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TR 1st Cap.
khanchan

12nd OCT 2020

WPD 2050422R326648

Accident date: 05th OCT 2020

Estimated repair cost for vehicle no: SLK5999K MERCEDES BENZ C200 (DEC 2017)

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear boot lid C200 logo		\$41.00 X
2	1	Rear boot lid EMBLE logo		\$80.00 X
3	1	Rear boot lid number plate		\$50.00 X
4	2	Rear Boot lid number plate lamp	\$155.00	\$310.00 X
5	1	Rear tail lamp-LH		\$950.00 X
6	1	Rear bumper		\$1,850.00 1550.
7	1	Rear bumper chrome		\$215
8	1	rear bumper lower cover		\$550.00 X
9	1	Rear bumper reverse sensor-SET		\$550.00 230.
10	10	Rear bumper clips	\$5.00	\$50.00 30
11	1	Rear Bumper lower garnish		\$355.00 ✓
Subtotal :-				\$5,096.40

Labour charges

To remove & re-fix cushion

To remove & re-fix reverse sensor

To Check Wiring System

Tuff kote

Panel beating

Spray painting

\$120.00 X

~~\$120.00~~ 50

~~\$80.00~~ 30

\$120.00 X

~~\$500.00~~ 250

~~\$500.00~~ 250

Subtotal :- \$1,440.00

Total :- \$6,536.40

Total: 2758

1/S: 2.2k

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: