



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0754/2020/NS
DATE : 9-Oct-20
WIP : 52516

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NG ZI HAO
ADDRESS : BLK 774 BEDOK RESERVOIR VIEW
#04-105
SINGAPORE 470774
TELEPHONE : HP +65 91559340
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700079236-02
VEHICLE NO : **SLU 5949 C**
MODEL CODE : AUDI SEDAN 1.4 TFSI S
MODEL YEAR : 7/12/2017
ENGINE NO : CVN 047470
CHASSIS NO : WAUZZZF45JA036156
MILEAGE : 38136KM
DATE IN : 9-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-20
PLACE OF ACCIDENT : TAMAN SIREH



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5949 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	✓ 250 ✓
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 350.00	✓ 280 ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,000.00	✓ 1500 ✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS WING MIRROR COVER.	\$ 2,950.00	✓ 2350 ✓ 4 X 550 = 2200 Mirror = 150
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 6,402.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Deformed</i>	\$	2,111.00	✓	1688.80
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	\$	282.00	x	
3	FRONT BUMPER SECURING STRIP <i>Not Nec</i>	2 \$	70.00	? x	
4	FRONT BUMPER GRILLE - CENTRE <i>Not in</i>	\$	194.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>	\$	208.00	+	
6	FRONT BUMPER AIR GUIDE - RH <i>Missing Deformed</i>	\$	62.00	x	49.50
7	RADIATOR GRILLE <i>Not in</i>	\$	1,139.00	x	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not in</i>	\$	134.00	✓	106.80
9	FRONT BUMPER CARRIER <i>Not Nec</i>	\$	795.00	x	
10	FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>	\$	37.00	-	29.50
11	FRONT BUMPER COVER <i>Not in</i>	\$	126.00	x	
12	FRONT BUMPER FOAM FILLER PIECE <i>Not in</i>	\$	123.00	x	
13	CAUTION SIGN STICKER <i>Not in</i>	NEC \$	14.00	+	
14	AIRCON STICKER <i>Not in</i>	NEC \$	8.00	+	
15	LOCK CARRIER BRACKET <i>Not in</i>	\$	136.00	+	
16	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>Not in</i>	\$	56.00	x	
17	HORN - RH LOW TONE <i>Not in</i>	\$	124.00	x	
18	SPRING SHACKLE - RH <i>Not in</i>	\$	29.00	+	
19	FRONT FENDER - RH <i>Distorted</i>	\$	758.00	✓	606
20	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	\$	200.00	x	
SUB TOTAL SPARE PARTS		:	\$	6,606.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	REMARKS
S/NETT			
21 FRONT FENDER CLOSING ELEMENT - RH	Best	\$	49.00 ? 39.00
22 FRONT FENDER BRACKET - RH	Best	\$	35.00 ✓ 27.60
23 DEFORMATION ELEMENT BRACKET - RH	Abc new	\$	49.00 ? X
24 FRONT FENDER INNER REAR BRACKET	Abc new	\$	31.00 ? X
25 FRONT FENDER BRACE - RH	Best	\$	117.00 ✓ 93.60
26 WHEEL HOUSING LINER - RH	Del d	\$	239.00 ✓ 190.80
27 WHEEL HOUSING LINER ATTACHMENT PARTS	AM not new	\$	90.00 ? X
28 WHEEL SPOILER	Torn	\$	73.00 ✓ 57.76
29 WHEEL SPOILER TRIM - RH	Abc new	\$	36.00 ? X
30 SONE CHIP GUARD - RH	new	\$	50.00 ✓ 39.92
31 TOP FENDER LEDGE COVER - INNER	Del d	\$	31.00 ? 24.40
32 TOP FENDER LEDGE COVER - OUTER	Del d	\$	23.00 ✓ 17.68
33 BONNET	Pented	\$	2,763.00 ✓ 2210.40
34 BONNET ATTACHMENT PARTS	new	\$	121.00 ✓ X
35 BONNET IMPACT PROTECTION - CENTRE	2	\$	27.00 ✓ 21.52
36 BONNET IMPACT PROTECTION - RH	new	\$	27.00 ✓ 21.52
37 BONNET IMPACT PROTECTION - LH		\$	28.00 ✓ 21.84
38 LED HEADLIGHT - RH	Cashed	\$	7,693.00 ✓ 6154.40
39 MAIN LIGHT ELECTRONICS POWER MODULE	2 not new	\$	739.00 X
40 LIGHT CONTROL SYSTEM CONTROL UNIT		\$	742.00 X
SUB TOTAL SPARE PARTS		:	\$ 12,963.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 LIFT CYLINDER - RH <i>Not Nec</i>		\$ 208.00	? X
42 EXTERIOR MIRROR MOUNTING - RH <i>lit</i>		\$ 886.00	✓ 708.80
43 MIRROR CAP - RH <i>Repair</i>		\$ 261.00	X.
44 WINDOW SLOT SEAL - RH <i>Not in</i>		\$ 303.00	+
45 FRONT ALUMINIUM RIM - RH <i>lit</i>		\$ 684.00	✓ 547.20
46 FRONT NO PLATE <i>Not in</i>	S/N	\$ 60.00	+
47 SUNDRIES <i>Nec</i>		\$ 300.00	? 38.72
TOTAL SPARE PARTS	:	\$ 22,271.00	
TOTAL LABOUR CHARGES	:	\$ 6,402.00	
GRAND TOTAL	:	\$ 28,673.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 12/10/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 06 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT