

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0754/2020/NS
DATE : 09-Oct-20
WIP : 52516

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

6 days - ok - Jy - 18 Dec 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NG ZI HAO
ADDRESS : BLK 774 BEDOK RESERVOIR VIEW
#04-105
SINGAPORE 470774
TELEPHONE : HP + 65 91559340
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700079236-02
VEHICLE NO : SLU 5949 C
MODEL CODE : AUDI SEDAN 1.4 TFSI S
MODEL YEAR : 07/12/2017
ENGINE NO : CVN 047470
CHASSIS NO : WAUZZZF45JA036156
MILEAGE : 38136KM
DATE IN : 09-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 08-Oct-20
PLACE OF ACCIDENT : TAMAN SIREH



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5949 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	280.00	\$	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$	350.00	\$	280.00
4	TO DISMANTLE AND RENEW RONT BUMPER, RHS FRONT FENDER, BONET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,000.00	\$	1,500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS WING MIRROR COVER.	\$	2,950.00	\$	2,350.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,402.00	\$	5,132.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,111.00	\$ 1,688.80
2	FRONT BUMPER FIXING PARTS		\$ 282.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 208.00	
6	FRONT BUMPER AIR GUIDE - RH		\$ 62.00	\$ 49.52
7	RADIATOR GRILLE		\$ 1,139.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 134.00	\$ 106.80
9	FRONT BUMPER CARRIER		\$ 795.00	
10	FRONT BUMPER GUIDE SECTION - RH		\$ 37.00	\$ 29.52
11	FRONT BUMPER COVER		\$ 126.00	
12	FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	
13	CAUTION SIGN STICKER	NEC	\$ 14.00	
14	AIRCON STICKER	NEC	\$ 8.00	
15	LOCK CARRIER BRACKET		\$ 136.00	
16	LOCK CARRIER BRACKET SUPPORT - LH / RH	2	\$ 56.00	
17	HORN - RH LOW TONE		\$ 124.00	
18	SPRING SHACKLE - RH		\$ 29.00	
19	FRONT FENDER - RH		\$ 758.00	\$ 606.00
20	FRONT FENDER ATTACHMENT PARTS		\$ 200.00	
SUB TOTAL SPARE PARTS		:	\$ 6,606.00	\$ 2,480.64

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
		<i>c/f</i>		\$	2,480.64
21	FRONT FENDER CLOSING ELEMENT - RH	\$	49.00	\$	39.20
22	FRONT FENDER BRACKET - RH	\$	35.00	\$	27.60
23	DEFORMATION ELEMENT BRACKET - RH	\$	49.00		
24	FRONT FENDER INNER REAR BRACKET	\$	31.00		
25	FRONT FENDER BRACE - RH	\$	117.00	\$	93.60
26	WHEEL HOUSING LINER - RH	\$	239.00	\$	190.80
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	90.00		
28	WHEEL SPOILER	\$	73.00	\$	57.76
29	WHEEL SPOILER TRIM - RH	\$	36.00		
30	SONE CHIP GUARD - RH	\$	50.00	\$	39.92
31	TOP FENDER LEDGE COVER - INNER	\$	31.00	\$	24.40
32	TOP FENDER LEDGE COVER - OUTER	\$	23.00	\$	17.68
33	BONNET	\$	2,763.00	\$	2,210.40
34	BONNET ATTACHMENT PARTS	\$	121.00		
35	BONNET IMPACT PROTECTION - CENTRE	\$	27.00	\$	21.52
36	BONNET IMPACT PROTECTION - RH	\$	27.00	\$	21.52
37	BONNET IMPACT PROTECTION - LH	\$	28.00	\$	21.84
38	LED HEADLIGHT - RH	\$	7,693.00	\$	6,154.40
39	MAIN LIGHT ELECTRONICS POWER MODULE	\$	739.00		
40	LIGHT CONTROL SYSTEM CONTROL UNIT	\$	742.00		
SUB TOTAL SPARE PARTS		:	\$	12,963.00	\$ 11,401.28

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<u>c/f</u>		\$ 11,401.28
41	LIFT CYLINDER - RH	\$	208.00	
42	EXTERIOR MIRROR MOUNTING - RH	\$	886.00	\$ 708.80
43	MIRROR CAP - RH	\$	261.00	
44	WINDOW SLOT SEAL - RH	\$	303.00	
45	FRONT ALUMINIUM RIM - RH	\$	684.00	\$ 547.20
46	FRONT NO PLATE	S/N \$	60.00	
47	SUNDRIES	\$	300.00	\$ 38.72
TOTAL SPARE PARTS		:	\$ 22,271.00	\$ 12,696.00
TOTAL LABOUR CHARGES		:	\$ 6,402.00	\$ 5,132.00
GRAND TOTAL		:	\$ 28,673.00	\$ 17,828.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

b1-09/12/20