

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305427346

Date : 14/10/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : STEVE CHEN

Vehicle Reg No. : SH 8585J

Date of Accident : 11-Oct-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJE9754D

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,026.06

(b) Labour Charges \$1,380.00

Total for Part-By-Part Repair Cost \$3,406.02

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : STEVE CHEN

Date : 16/10/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.10.2020

Time: 14:29:58

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427346
REGN NO : SH 8585J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 11.10.2020 17:23
ACCIDENT DATE : 11.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	REAR BUMPER CENTER-Black	1	451.25	20.00	361.00
0003	04-01-0104-2545-G	RR BUMPER LWR CTR MLDING	1	155.00	20.00	124.00
0004	04-01-0104-2546-G	RR BUMPER SIDE UDR CVR LH	1	108.00	20.00	86.40
0005	04-01-0104-2531-G	REAR BUMPER SIDE BRKT LH	1	33.10	20.00	26.48
0006	04-01-0104-2697-G	TAILLAMP LH	1	870.40	20.00	696.32
0007	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0008	04-01-0104-2467-G	FRT DOOR LWR MOULDING LH	1	116.20	20.00	92.96
0009	04-01-0104-2469-G	REAR DOOR LWR MOULDING LH	1	116.20	20.00	92.96
0010	28-01-0103-0003-A	Frt Door ComfortDelGro LH	1	75.00	10.00	67.50
0011	28-01-9999-2023-A	REAR DOOR APPS STICKER LH	1	80.00	10.00	72.00
0012	04-01-0104-3813-G	FRT FENDER BLUE-DRIVE LH	1	26.60	20.00	21.28

SUB-TOTAL : 2,026.02

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.10.2020

REPAIR ESTIMATE

Time: 14:29:58

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427346
REGN NO : SH 8585J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 11.10.2020 17:2
ACCIDENT DATE : 11.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT-Frt Fender LH etc	1000.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 L	R/I REVERSE SENSOR	30.00

SUB-TOTAL : 1,380.00

TOTAL : 3,406.02


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :