

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM20011044/Aea3q2	
	8 SHENTON WAY AXA TOWERSING		Date:	19/01/2022	
	ATTN:CYNTHIA		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 9681Z	Veh. Inspected	SJH 682X	
	Policy No.	P2382948	Coverage (\$)	0.00	
	Claim No.	S0M02VDQ	Excess (\$)	0.00	
	Assign From		Assign Date	12/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ACCORD	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	CL73304694	Colour	GREY	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/10/2020	Inspection Date	12/10/2020	
	Survey held at	NEW ZEN WERKZ PTE LTD			
	3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				