

MBM WHEELPOWER PTE LTD

SLT4120M
SDU8722P

MSIG Insurance (Singapore) Pte. Ltd.

*Not Withheld
11 Pm @ 4950/-
Repair After Rain
3 days*

Date: 14/10/2020
From: Eryx Tan
Fax: 64525333
Contact: 8138 7188
Make / Model: JAGUAR XJ 3.0 DIESEL LWB PL
AT ABS D/AB HID EU4
Engine No.: 0549046306DT
Chassis No.: SAJAC2253BNV21320
Year of Make: 2011
Accident Date: 21 August 2020



TE FOR VEHICLE NO.: SDU8722P

DESCRIPTION	QTY	List Price
FRONT BUMPER <i>2550</i>	1	\$ <i>msm</i> 3,650.00 ✓
FRONT BUMPER SIDE RETAINER LH	1	\$ <i>sn</i> 90.00 X
FRONT BUMPER SIDE RETAINER RH	1	\$ <i>cm</i> 90.00 ✓
FRONT BUMPER FOG LAMP GARNISH RH	1	\$ <i>sn</i> 380.00 X
FRONT BUMPER FOG LAMP GARNISH CHROME TRIM RH	1	\$ <i>sn</i> 420.00 X
FRONT BUMPER LOWER SPOILER RH	1	\$ <i>sn</i> 580.00 X
FRONT BUMPER RADIATOR GRILLE	1	\$ <i>sn</i> <i>1250</i> X
FRONT BUMPER RADIATOR GRILLE LOGO	1	\$ 135.00 X
FRONT FENDER RH	1	\$ <i>n</i> 2,350.00 X
FRONT FENDER INNER GARNISH RH	1	\$ <i>sn</i> 585.00 X
HEADLAMP RH <i>3510</i>	1	\$ <i>cm</i> 4,650.00 ✓
BONNET	1	\$ <i>n</i> 5,850.00 X
BONNET HINGE LH	1	\$ <i>n</i> 165.00 X
BONNET HINGE RH	1	\$ <i>n</i> 165.00 X

Total: \$ 19,110.00
LESS 10% \$ (1,911.00)
Parts Total: \$ 17,199.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

HOUR
 REMOVE, REFIT & REPAIR REAR DAMAGED PORTIONS.
 CHECK & RECONNECT ALL NECESSARY WIRING
 RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)
 REMOVE & REPLACE BUMPER SENSORS
 PRAY PAINT ON THE AFFECTED AREAS

\$	800.00	300l
\$	120.00	20l
\$	150.00	un
\$	60.00	60l
\$	800.00	300l

Total: \$	19,129.00
7% GST: \$	1,339.03
Grand Total: \$	20,468.03