# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Irene Tay Hui Ping Date: 15 Dec 2020

# **Preliminary Advice**

Insured Vehicle No : GBH5964U

TP Vehicle No : SLE801L Accident Date : 09/10/2020 Make : VOLKSWAGEN GOLF Assignment Date : 13/10/2020

: 3 Date of Inspection : 13/10/2020 Est. Duration of Repair

Inspection At : GARAGE 13 PTE. LTD. (HQ)

8 KAKI BUKIT AVENUE 4, #03-46 PREMIER

SINGAPORE 415875

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,010.00
Revised Amount	:S\$	2,111.59
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,111.59
Lump Sum Repair	:S\$	2,100.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Survey on WP ( X )