GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 SINGAPORE 415875 STEN (LKK) m M , 13/10/00, 11.00an Accident Date: 09/10/2020 19:55 Vehicle No: SLE 801 L Model No. VOLKSWAGEN GOLF Owner: LI JUN Chassis no. * WVWZZZAUZKW087477 Date of Estimate: 13/10/2020 Estimate for Accident Vehicle No. SLE 801 L Unit Price Total Amount List Items: Qty \$1,350.00 1/65-55/ 1 Rear Bumper / 1 \$1,350.00 \$540.00 3 20 2 Rear Bumper Spoiler / TN \$540.00 3 Rear Bumper Reflector LF X \$110.00 X \$110.00 4 Rear Bumper Parking Sensor / Shirt \$570.00 205/ 21 \$285.00 Rear Bumper Chrome Stripe LF / CVT \$200.00 160/ \$200.00 Rear Bumper Chrome Stripe Center / 11 \$280.00 774 6 \$280.00 \$170.00 136 Rear Bumper Center Bracket / SR 7 1 **\$170.00** 2210.55 Rear Bumper Enforcement **\$**940.00 X 8 \$940.00 -10% 9 10 1989-49 Sub-Total Amount = \$4,160.00 Less parts-discount = 0% \$0.00 Sub-Total = \$4,160.00 Special Nett Items Qty Unit Price **Total Amount** 1 Sub-Total = \$0.00 Total cost for parts = \$4,160.00 Labour charges

1	Panel Beating and	l replacement	of damag	ged part
2	C D:			

2 Spray Painting

3

4

⁵LKK Auto Consultants hence notify 6 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) dunna resurvey
- Parts prices are subject to make a
- Third party survey is since the pice to
- No illegal modification is a
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

part: 1	500		\$500.00	300
1	350		\$350.00	1/
P- 190	89-49		\$0.00	
L- 6	,		\$0.00	
L- 01	39-49		\$0.00	150
			\$0.00	650
L/S - 2111 = 219	-59		\$850.00	a la
- 219	9		* 24 To a co	1 2 2
	l parts	=	\$4,160.00	
Total	Total labour		\$850.00	
Tota	d Amount	= -	\$5,010.00	Ð