

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Oct-20

INSURANCE: China Triping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 7859 T

Description	Qty	List Price	Amount
Bonnet <i>Devald</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>ren</i>	2	\$ 118.70	\$ 237.40
Bonnet Lock <i>st</i>	1	\$ 127.30	\$ 127.30
Bonnet Insulator <i>HW</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>HW</i>	1	\$ 15.00	\$ 15.00
Bonnet Cable LONG <i>HW</i>	1	\$ 135.60	\$ 135.60
Bonnet Cable SHORT <i>HW</i>	1	\$ 59.90	\$ 59.90
Radiator Grille NEW MODEL <i>crack</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>crack</i>	2	\$ 824.60	\$ 1,649.20
Front bumper top cover <i>crack</i>	1	\$ 476.30	\$ 476.30
Front Bumper Moulding Centre Upper <i>minorly crack</i>	1	\$ 368.50	\$ 368.50
Front Bumper Bracket Top (LH/RH) <i>HW</i>	2	\$ 35.00	\$ 70.00
Front Bumper Clips 10 pcs <i>HW</i>	1	\$ 25.00	\$ 25.00
Headlamp Support Panel Assy <i>broken</i>	1	\$ 949.30	\$ 949.30
Headlamp(LH/RH) <i>crack</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>HW</i>	2	\$ 72.80	\$ 145.60
Horn Wire <i>HW</i>	1	\$ 386.70	\$ 386.70
Radiator <i>st</i>	1	\$ 710.50	\$ 710.50
Radiator Inverter <i>st</i>	1	\$ 884.80	\$ 884.80
COOLANT <i>HW</i>	1	\$ 45.00	\$ 45.00
Radiator fan blower motor assy <i>broken</i>	1	\$ 1,226.60	\$ 1,226.60
Aircon Condenser <i>st</i>	1	\$ 663.60	\$ 663.60
Air Cleaner Assy <i>broken</i>	1	\$ 1,336.50	\$ 1,336.50
Air Duct <i>deformed / broken</i>	1	\$ 156.80	\$ 156.80
Air Cleaner hose <i>deformed</i>	1	\$ 86.40	\$ 86.40
SUB TOTAL			\$ 21,783.10
LESS 20%			\$ 4,356.62
DISCOUNTED TOTAL			\$ 17,426.48
Labour Charge			
Panel Beating	1	\$1,400.00	\$1,400.00
Spray Painting Charge	1	\$1,200.00	\$1,200.00
Wiring Charge	1	\$160.00	\$160.00
Tuff Kote	1	\$140.00	\$140.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$3,750.00

ESTIMATE TOTAL			\$21,176.48
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

14/10/2020 @ 09:15 hrs

N/A Arthur
Part by Part.

you 15 days.

LKK Auto

Photo after
repair with
damaged parts.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: