

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

TP111

12nd OCT 2020

8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

Acilia

JF1SJSK65JG110463

Accident date:
Estimated repair cost for vehicle no: SMC1320A SUBARU FORESTER

S/n	Qty	Items	U/price	Amount
				\$1,252.20 ✓
1	1	Rear Boot Lid <i>Dented</i>		\$285.20 X
2	1	Rear boot lid inner lock <i>new</i>		\$122.20 ✓
3	1	Rear boot lid windscreen moulding <i>new</i>		\$83.60 ✓
4	1	Rear boot lid emble logo		\$60.00 ✓
5	1	rear Boot Lid subaru logo <i>new</i>		\$49.50 ✓
6	1	Rear boot lid forester logo		\$425.10 ✓
7	1	Rear boot lid inner trim board <i>cracked.</i>	\$566.20	\$1,132.40 <i>A37</i>
8	2	Rear tail lamp <i>RH cracked.</i>		\$544.00 X
9	1	Rear fender inner trim board-RH <i>new</i>	\$5.60	\$44.80 X
10	8	Rear fender inner trim board clips		\$950.00 <i>710</i>
11	1	Rear Bumper <i>Distorted</i>	\$55.20	\$110.40 <i>55.20</i>
12	2	Rear bumper reflector <i>RH cracked</i>	\$88.20	\$176.40 <i>35</i>
13	2	Rear Bumper Side Bracket <i>RH Dented</i>		\$155.20 X
14	1	Rear Bumper Inner Sponge <i>new</i>	\$5.60	\$44.80 ✓
15	8	Rear bumper clips <i>new</i>		\$425.00 ✓
16	1	Rear bumper reinforcement <i>Bent</i>		\$350.00 <i>200 (SN)</i>
17	1	Rear Bumper reverse sensor <i>Dented</i>		\$65.00 X
18	1	Rear bumper towing cover <i>new</i>		\$422.60 ✓
19	1	Rear bumper top chrome panel <i>Distorted</i>		\$288.00 ✓
20	1	Rear Bumper lower garnish <i>Distorted</i>		\$325.00 X
21	1	rear bumper lower cover <i>new</i>		\$462.30 ✓
22	1	Rear End Panel <i>Distorted</i>		\$285.00 X
23	1	END panel top garnish <i>new</i>		\$855.00 ✓
24	1	Rear exhaust silencer <i>Dented</i>		\$974.00 X
25	1	Rear exhaust centre pipe <i>new</i>		\$185.00 ✓
26	1	Rear exhaust chrome pipe <i>Bent</i>	\$45.00	\$135.00 X
27	3	Rear exhaust mounting <i>new</i>		
Subtotal :-				\$10,207.70

5912.5

A730

SN:200

Labour charges

Remove & refix rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

Remove & refix rear cushion

~~\$120.00~~ 60

Remove & refix rear reverse sensor

~~\$120.00~~ 50

tuff Kote

~~\$120.00~~ 60

To Check Wiring System

~~\$60.00~~ 30

to remove & Refix rear exhaust

~~\$280.00~~ 80

Panel beating

~~\$900.00~~ 80

Spray painting

~~\$900.00~~ 80

subtotal:- \$2,670.00

Total:- \$12,877.70

total: 6880

L/S: 5.5k.

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: