



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6881S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PRIG4 COVER FRONT BUMPER	TO REPAIR SEE LABOUR	499.90	-
10	PRIVC BUMPER PIRCE	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-130.48	-
			391.42	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PRIG4 COVER FRONT BUMPER.		320.00	160.00
	SPRAY PAINT ON AFFECTED AREA.		250.00	200.00
			570.00	360.00
GRAND TOTAL			961.42	360.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				360.00

Report Ref No. NS/INC20011063/Etd3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.