

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0763/2020/NS  
DATE : 12-Oct-20  
WIP : 52758

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

## **AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**  
**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR LOW KOK CHEONG ATTICUS  
ADDRESS : 10 HOUGANG STREET 32  
#08-24  
SINGAPORE 534037  
TELEPHONE : HP +65 97927926  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1700069824-02  
VEHICLE NO : **SLT 3704 K**  
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S  
MODEL YEAR : 26/10/2017  
ENGINE NO : CVN 045413  
CHASSIS NO : WAUZZZF41JA022951  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 10-Oct-20  
PLACE OF ACCIDENT : AFTER SLIP ROAD FROM KPE TO TAMPINES ROAD



**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 3704 K**

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ <del>700.00</del>	250.
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>2,000.00</del>	1500
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS UPPER A-PILLAR.	\$ <del>2,850.00</del>	1650
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 6,022.00</u></b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 3704 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>deformed</i>		\$	2,111.00	✓
2	FRONT BUMPER FIXING PARTS <i>not in</i>		\$	282.00	x
3	FRONT BUMPER SECURING STRIP ?	2	\$	70.00	?
4	FRONT BUMPER GRILLE - CENTRE <i>crushed</i>		\$	194.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>not in</i>		\$	208.00	x
6	RADIATOR GRILLE <i>crushed</i>		\$	1,799.00	✓
7	FRONT BUMPER AIR GUIDE - LH / RH <i>not in</i>	2	\$	722.00	361.
8	FRONT BUMPER FOAM FILLER PIECE ?		\$	123.00	?
9	FRONT BUMPER CARRIER ?		\$	795.00	?
10	FRONT BUMPER TOP COVER <i>not in</i>		\$	126.00	x
11	FRONT BUMPER GUIDE SECTION - LH <i>not in</i>		\$	36.00	+
12	FRONTBUMPER GUIDE SECTION - RH <i>not in</i>		\$	37.00	f
13	CAUTION SIGN STICKER <i>not in</i>	NEC	\$	14.00	+
14	AIRCON STICKER <i>not in</i>	NEC	\$	8.00	+
15	LOCK CARRIER BRACKET ?		\$	136.00	?
16	LOCK CARRIER BRACKET SUPPORT - LH / RH ?	2	\$	56.00	?
17	BONNET <i>Dented</i>		\$	2,763.00	✓
18	BONNET ATTACHMENT PARTS <i>not in</i>		\$	121.00	+
19	BONNET LID HINGE - LH / RH <i>not in</i>	2	\$	602.00	x
20	BONNET IMPACT PROTECTION - CENTRE <i>not in</i>		\$	27.00	✓
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 10,230.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 3704 K**

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 BONNET IMPACT PROTECTION - LH	1	\$ 28.00	✓
22 BONNET IMPACT PROTECTION - RH	1	\$ 27.00	✓
23 BONNET STRIKER - LH / RH	2	\$ 100.00	+
24 BONNET LID LOCK	2	\$ 423.00	+
25 BONNET BOWDEN CABLE - INNER	1	\$ 57.00	+
26 BONNET BOWDEN CABLE - OUTER	1	\$ 57.00	+
27 FRONT FENDER - LH	1	\$ 758.00	✓
28 FRONT FENDER ATTACHMENT PARTS	1	\$ 200.00	+
29 FRONT FENDER CLOSING ELEMENT - LH	1	\$ 49.00	+
30 FRONT FENDER BRACKET - LH	1	\$ 35.00	+
31 FRONT FENDER BRACE - LH	1	\$ 117.00	+
32 WHEEL HOUSING LINER - LH	1	\$ 237.00	+
33 WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 90.00	+
34 WHEEL SPOILER	1	\$ 73.00	+
35 WHEEL SPOILER TRIM - LH	1	\$ 35.00	+
36 STONE CHIP GUARD - LH	1	\$ 50.00	✓
37 TOP FENDER LEDGE COVER - UPPER	1	\$ 31.00	?
38 TOP FENDER LEDGE COVER - LOWER	1	\$ 23.00	?
39 LED HEADLIGHT - LH / RH	2	\$ 15,386.00	7693
40 LIFT CYLINDER - LH / RH	2	\$ 416.00	+
<b>SUB TOTAL SPARE PARTS</b>	<b>:</b>	<b>\$ 18,192.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 3704 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 RADIATOR AIR GUIDE - LH / RH	2	\$	56.00	x
42 RADIATOR AIR GUIDE - LH / RH	2	\$	24.00	x
43 RADIATOR AIR GUIDE - UPPER		\$	16.00	x
44 RADIATOR AIR GUIDE - LOWER		\$	22.00	x
45 FRONT NO PLATE <i>Beit</i>	S/N	\$	60.00	✓
46 SUNDRIES <i>?</i>	S/N	\$	300.00	?
<b>TOTAL SPARE PARTS</b>	:	<b>\$</b>	<b>28,900.00</b>	
<b>TOTAL LABOUR CHARGES</b>	:	<b>\$</b>	<b>6,022.00</b>	
<b>GRAND TOTAL</b>	:	<b>\$</b>	<b>34,922.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*  
SURVEYED DATE : *13/10/20*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT