



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM20011081/Bps3q2 Date: 10/03/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	E 2020C	Veh. Inspected	SGY 6376L	
Policy No.	GA151518	Coverage (\$)	0.00	
Claim No.	S0M02V6Y	Excess (\$)	0.00	
Assign From		Assign Date	13/10/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ R350L	c.c	3498	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDC2511652A142575	Colour	BLACK	
Odometer	112900 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	255/55 R18	MULTIVAN	6 mm	
L/H Front Tyre	255/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	255/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	255/55 R18	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/10/2020	Inspection Date	13/10/2020	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	