

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SGY 6376 L**

Model : Mercedes R350

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2012

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Front bumper	1	\$ 1,997.31	\$ 1,453.00 1,997.31	BRV
2	Front bumper side retainer	2	\$ 96.25	\$ 148.80 192.50	NEC
3	Front bumper fog lamp	1	\$ 119.97	\$ 119.97	
4	Front bumper fog lamp outer garnish	1	\$ 158.60	\$ 158.60	NDX
5	Front bumper parking sensor	1	\$ 292.95	\$ 215.00 292.95	SCV
6	Front fender LH	1	\$ 1,408.51	\$ 516.80 1,408.51	DDV
7	Front fender inner cowl LH	1	\$ 375.00	\$ 375.00	NDX
8	Bonnet	1	\$ 2,738.35	\$ 2,738.35	CUTXR
9	Bonnet logo	1	\$ 74.91	\$ 82.80 74.91	NEC
10	Headlamp LH	1	\$ 1,454.94	\$ ✓ 1,454.94	CUTV
11	Headlamp lower bracket LH	1	\$ 968.16	\$ 968.16	NSX
12	Front door LH	1	\$ 3,693.04	\$ 1,446.00 3,693.04	DDV
13	Front door outer garnish	1	\$ 210.88	\$ ✓ 210.88	CUTV
14	Front door weatherstrip	1	\$ 243.72	\$ 243.72	NDX
15	Front door regulator assy	1	\$ 713.98	\$ 713.98	
16	Front door regulator motor	1	\$ 499.95	\$ 499.95	
17	Front door inner lock	1	\$ 1,047.34	\$ 1,047.34	
18	Front door lock striker	1	\$ 35.00	\$ 35.00	NDX
19	Front door hinge	2	\$ 162.00	\$ 324.00	
20	Front door inner trimboard	1	\$ 1,675.04	\$ 1,675.04	
21	Front door frame rubber	1	\$ 273.11	\$ 273.11	
22	Rear door LH	1	\$ 3,534.48	\$ 3,534.48	CUTXR
23	Rear door outer garnish	1	\$ 210.88	\$ ✓ 210.88	CUTV
24	Rear door weatherstrip	1	\$ 269.02	\$ 269.02	
25	Rear door regulator assy	1	\$ 736.14	\$ 736.14	
26	Rear door regulator motor	1	\$ 479.62	\$ 479.62	
27	Rear door glass channel	1	\$ 350.00	\$ 350.00	
28	Rear door outer chrome garnish	1	\$ 228.24	\$ 228.24	NDX
29	Rear door inner lock	1	\$ 1,047.34	\$ 1,047.34	
30	Rear door lock striker	1	\$ 35.00	\$ 35.00	
31	Rear door checker arm	1	\$ 61.00	\$ 61.00	
32	Rear door inner trimboard	1	\$ 1,480.50	\$ 1,480.50	
33	Rear door frame rubber	1	\$ 170.73	\$ 170.73	
34	Front shock absorber LH	1	\$ 835.20	\$ 835.20	
35	Front lower arm LH	1	\$ 1,644.70	\$ 1,644.70	NDX
36	Front Upper arm LH	1	\$ 886.86	\$ 886.86	
37	Front knuckle arm LH	1	\$ 2,196.66	\$ 2,196.66	
38	Front knuckle arm bearing LH	1	\$ 430.00	\$ 336.80 430.00	JM
Parts Sub Total :				\$ 5861.82 33,093.63	
Discount 10% :				\$ 586.18 3,309.36	
PARTS TOTAL :				\$ 29,784.27	

5275.64

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Front bumper clips	1	\$ 60.00	\$ 60.00	NSX
3	Front bumper fog lamp outer garnish clips	1	\$ 60.00	\$ 60.00	KDX
4	Front bumper parking sensor seal	1	\$ 68.00	\$ 68.00	WTV ✓
5	Front fender sealant	1	\$ 100.00	\$ 30.00	✓ NEC
6	Front fender inner cowling clips	1	\$ 60.00	\$ 60.00	NNX
7	Bonnet sealant	1	\$ 100.00	\$ 100.00	NNX
8	Front door sealant	1	\$ 100.00	\$ 50.00	NECV ✓
9	Front door outer garnish clips	1	\$ 60.00	\$ 30.00	NECV ✓
10	Front door inner trim board clips	1	\$ 60.00	\$ 30.00	NECV ✓
11	Rear door sealant	1	\$ 100.00	\$ 100.00	NNX
12	Rear door outer garnish clips	1	\$ 60.00	\$ 30.00	NECV ✓
13	Rear door inner trim board clips	1	\$ 60.00	\$ 60.00	NNX
14	Front Alloy rim	1	\$ 1,100.00	\$ 250.00	WTVR ✓
15	Front Tyre	1	\$ 480.00	\$ 480.00	KDX
SPECIAL NETT TOTAL :				\$ 488.00	2,888.00

Nos.	LABOUR	S\$	
1	R&R Front bumper parking sensor	\$ 60.00	100.00 ✓
2	R&R front door component	\$ 80.00	200.00 ✓
3	R&R rear door componnet	\$	200.00 NNX
4	R&R front undercarriage	\$ 260.00	450.00 ✓
5	R&R front tyre and balancing	\$ 60.00	200.00 ✓
6	Wheel alignment.	\$ 60.00	120.00
7	Upholstery	\$	300.00 NNX
8	Check wiring	\$ 50.00	100.00 ✓
9	Rust proofing	\$	200.00 NNX
10	Diagnostic reset fault code	\$ 150.00	300.00 NECV ✓
11	Panel beat	\$ 1000.00	1,800.00 ✓
12	Spray paint	\$ 1800.00	1,800.00 ✓
LABOUR TOTAL :		\$	5,770.00

Survey 13/10/2020
 Resurvey 14/10/2020
 Team Tim
 Team Tim
 1430 hrs 1240 hrs

PARTS TOTAL : \$ 29,784.27
 SPECIAL NETT TOTAL : \$ 2,888.00
 LABOUR TOTAL : \$ 5,770.00
 GRAND TOTAL : \$ 38,442.27

PARTS 5275.64
 S/N 488.00
 LABOUR 2660.00
 8423.64
 @2090 1684.73
 6738.91

Lump sum repair
 Repair days 8

L/S 6,700/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Team Tim
 12/10/2020