

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Date: 29/12/2020

FRESH CLEANING PTE LTD,

1014, Geylang East Ave 3, #05-240

SINGAPORE 389729

Veron.

1598cc

Accident Date: 07/10/2020

ZFA26300006H45893. 2018 July.

Estimate Cost of Repair Bill To Fiat Doglo Van NO: GBH 5579 Z

1 pc Front Bonnet Dented	1170 ✓
1 pc Front R/H Headlamp cracked	862.40 ✓
1 pc Front R/H Headlamp Bracket New	95 X
1 pc Front Grille Cracked	844.70 ✓
1 pc Front Grille Emblem New	115.70 ✓
1 pc Front Bumper (Top) Dented	864.20 ✓
8 pc Front Bumper clip new	30 ✓
1 pc Front Bumper (Lower) Cracked	685 ✓
2 pc Front Bumper side Retainer New	150 ✓
1 pc Front Bumper R/H side Garnish Cut	188.20 ✓
1 pc Front Bumper sponge Cracked	117.60 ✓
1 pc Front Bumper Reinforcement Beam Not New	752 X
1 pc Front No. plate Best	✓ \$26 s/nct
1 pc Front No. plate cover Defund	✓ \$26 s/Nett
1 pc Front No. plate Garnish Cracked	95 ✓

5661.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Estimate Cost of Repair Bill To Fiat Doglo Van NO: GBH 5579Z

1pc Rear L/H Bootlid Dented	2355.50 ✓
2pc Rear L/H Bootlid Hinge @ 116.30 New	232.60 X.
4pc Rear Bootlid Emblem New	280 ✓
1pc Rear 70 km/h sticker ?	✓ \$15 s/NeH
1pc Rear 6 pax sticker } New	✓ \$15 s/NeH
1pc Rear L/H Bootlid Lock Damaged	244.60 ✓
1pc Rear L/H Bootlid Handle Garnish Cracked	462.90 ✓
1pc Rear L/H Bootlid Inner Trimboard Cracked	288.70 ✓
1pc Rear Bootlid Rubber cut cut.	286.40 ✓
1pc Rear L/H Taillamp cut	422.10 ✓
1pc Rear End panel Dented	430 ✓
1pc Rear End panel Garnish Del'd	347.70 ✓
1pc Rear Bumper Distorted	734.30 ✓
8pc Rear Bumper Clip New	30 ✓
2pc Rear Bumper Side Retainer New	150.80 ✓
2pc Rear Bumper Reflector L/H cut	234 117.
1pc Rear Bumper Reinforcement Beam Bent	520.90 ✓
1pc Rear Reverse Camera Damaged	✓ \$380 s/NeH
1 set Rear Reverse Sensor Damaged	✓ \$200 s/NeH
1pc Rear L/H Windscreen Inner seal ?	✓ \$26 s/NeH
1pc Rear L/H Windscreen sealant } New	✓ \$45 s/NeH
1pc Rear L/H Windscreen moulding	✓ \$60.00
1pc Rear No. plate	X \$26 s/NeH
1pc Rear No. plate cover } New	X \$26 s/NeH

7813.50

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Estimate Cost of Repair Bill To Fiat Doglo Van NO: GBH5579Z

To Check Wiring

\$50.00 ✓

To Spray Painting

1400
~~\$1,600.00~~

To Remove & Retix Rear Windscreen

~~\$150.00~~
80.

To Measure, Drill The Replaced Rear Bumper, Position
& Reinstall Rear Reverse Sensor, Control Unit, Camera
& Test For Functioning

\$80 ✓

To Supply and Install For Fiat Doglo Van sticker

2pc Rear Bootlid, 1pc Rear L/H Fender, Rear Bumper

1pc Front Bumper, 1pc Front R/H Fender & Bonnet

Labour Charge for Removal and Cleaning of Stains

Sticker Code Oracal 910 ra

✓
\$1,200 s/Ne

To Supply Art work design

Invoice Number: 5412

Labour Charge For Panel Beating, Removing All

Damage Parts & Replacing of The New Parts Etc

✓
\$1,200.00

4280

List: 1149370 Labour: 4010

Less 10%: 10344.33 total: 1508733.

S.N: 733

2/s: 12050.

11 Days.

17,755.30

INVOICE

Amount Due (SGD)
\$1,200.01

BILL TO
TK workshop
Ah Keong

96273323

Invoice Number: 5412

Invoice Date: October 26, 2020

Payment Due: October 26, 2020

ITEMS	QUANTITY	PRICE	AMOUNT
Oracal 970ra To supply and install for Fiat Diablo	1	\$1,121.50	\$1,121.50
2 x rear boot			
1 x rear Bumper			
1 x rear fender			
4 x Custom printing of company logos			
1 x Labour charges for removal and cleaning of stains			
1 x artwork design			

Subtotal: \$1,121.50

GST 7%: \$78.51

Total: \$1,200.01

Amount Due (SGD): \$1,200.01

Notes / Terms

SuperFun Pte Ltd

GST registration number: 201808730D

All price inclusive of GST

Singapore Bank Details

DBS CURRENT ACCOUNT: 023-90619-40

Paynow, please enter this UEN number for transfer 201808730D

SuperFun 超好玩

Superfun Pte Ltd (UEN NO:
201808730D)

1991/194 หมู่บ้านเอเวอริสตา ถนนเดชาธินา
สุขุมวิท 77 ถนน อ่อนนุช แขวงสวนหลวง
เขตสวนหลวง กรุงเทพฯ 10250 10250.
(Thailand)
31 Woodlands Close #02-23, S737855
(Singapore)
Page 1 of 2 for Invoice #5412
Singapore

Contact Information
+65 86088386

INVOICE

Amount Due (SGD)
\$1,200.01