



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
T K MOTOR WORKSHOP			Ref:	CS/TP20011082/Avd3e2
BLK 1 KAKI BUKIT AVE 6 #02-56SINGAPORE 417883			Date:	12/05/2021
ON BEHALF OF FRESH CLEANING PTE LTD			Code:	TP179
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	GBH 5579Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	09/10/2020	
2. Vehicle Particulars & Condition				
	Make & Model	FIAT DOBLO	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZFA26300006H45893	Colour	YELLOW
	Odometer	87790 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/10/2020	Inspection Date	09/10/2020
	Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	