

LC AUTOMOTIVE

Block 25 KAKI BUKIT ROAD 4 #05-26 SYNERG @KB (S)417800

Tel : (65) 65250431 HP: 92712214

Email : chris_chanbebe@hotmail.com

12th OCT 2020

25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

TP 1st Cap.
Khanchner.

MR053REH104540373

Accident date: 12nd OCT 2020

Estimated repair cost for vehicle no: SKX7999R TOYOTA COROLLA ALTIS 1.6

S/n	Qty	Items	U/price	Amount
				\$1,050.00 X
1	1	Front bonnet		\$215.00 X
2	1	Front bonnet lock		\$155.00 X
3	1	Front bonnet inner rubber		\$77.40 X
4	6	Front bonnet inner rubber clips	\$12.90	\$188.00 X
5	1	headlamp top chrome -LH		\$1,250.00 ✓
6	1	Front headlamp -LH		\$315.00 X
7	1	Front grille		\$50.00 X
8	1	grille clips		\$65.00 X
9	1	Front grille emble logo		\$820.00 458
10	1	Front bumper		\$246.40 45
11	2	Front Bumper Side Bracket	\$123.20	\$103.20 30
12	8	Front bumper clips	\$12.90	\$50.00 X
13	1	Front bumper number plate		\$182.00 ✓
14	1	Front bumper inner sponge		\$270.00 X
15	2	front bumper side bracket	\$135.00	\$330.40 X
16	2	front bumper side retainer	\$165.20	\$155.00 ✓
17	1	Front bumper fog lamp cover-LH		\$254.00 ✓
18	1	Front fog lamp -LH		\$258.00 ✓
19	1	Front air-con cleaner -top		\$265.00 ✓
20	1	front air-con cleaner -lower		\$725.00 ✓
21	1	Front fender -LH		\$153.90 X
22	1	Front fender mud shield -LH		\$184.00 ✓
23	1	Front fender inner cowling		\$103.20 30
24	8	Front fender cowling clips	\$12.90	\$300.00 X
25	1	Front tyre-LH		\$400.00 ✓
26	1	Front sport rim-LH		\$325.00 ✓
27	1	Front shock absorber		\$265.00 ✓
28	1	Front knuckle arm-LH		\$285.00 ✓
29	1	Front lower arm-LH		\$188.00 ✓
30	1	Front wheel bearing-lh		

Subtotal :- \$9,228.50

5487
4115.25

Labour charges

To remove & refit cushion

To remove & refit front undercarriage

To check wheel alignment computer

To check wiring

To remove & re-fix front air cleaner & top up gas

Tuff kote

Panel beating

Spray painting

\$120.00 X

~~\$280.00~~ 200

~~\$150.00~~ 80

~~\$80.00~~ 30

\$150.00 X

\$120.00 X

~~\$1,000.00~~ 500

~~\$1,000.00~~ 600

Subtotal :- \$2,900.00

Total :- \$12,128.50

total: \$525.25

4/s: 4.4k.

05 Days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

VIN:
Date

SKX 7999 R
12.10.20 12:51



SKX 7999 R

TOYOTA ALTIS 2014-

Front : Left

Actual	Before	Specified Range
-1°30'	-1°30'	-0°59' 0°31'
3°08'	3°08'	5°08' 6°38'
-0°19'	-0°19'	0°00' 0°11'
21°11'	21°11'	
19°41'	19°41'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°14'	-0°14'	-0°59' 0°31'
3°35'	3°35'	5°08' 6°38'
-0°16'	-0°16'	0°00' 0°11'
8°23'	8°23'	
8°09'	8°09'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-1°15'	-1°15'	-0°45' 0°45'
-0°27'	-0°27'	-0°45' 0°45'
12°47'	12°47'	
-0°35'	-0°35'	0°00' 0°22'

Rear : Left

Actual	Before	Specified Range
-1°40'	-1°40'	-1°58' -0°58'
0°10'	0°09'	-0°01' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°20'	-1°20'	-1°58' -0°58'
0°01'	0°00'	-0°01' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°21'	-0°21'	-0°30' 0°30'
0°11'	0°09'	-0°01' 0°31'
0°04'	0°05'	