



南方摩哆

Business Reg. No: 234147.00L
 Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
 Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30-Sep-20
 China Taiping Insurance Singapore Pte Ltd
 3 Anson Road #16-00
 Springleaf Tower
 Singapore (079909)

Dear Sirs,

RE: Cost of repair to Yamaha FZN150- FBK5709A

1pc of Front Mudguard	S\$	55.00	cut ✓
1pc of Handle Bar	Xnn	65.00	?
1pc of Fuel Tank Cover		180.00	cut ✓
1pc of Side Box RH silver colour.		110.00	cut ✓
2pcs of Centre Fairing	\$55 LH Xnn	10.00	LH, RH cut ✓
1pc of Handle Balancer		25.00	cut ✓
1pc of Brake Lever		20.00	cut ✓
1pc of Exhaust Pipe w/cover x2 (1set)		480.00	cut ✓
1pc of Front Footrest		35.00	cut ✓
1pc of HeadLamp Cover		110.00	cut ✓
		<u>1,190.00</u>	
		119.00	
		<u>1,071.00</u>	
		30.00	✓
	Xnn	165.00	✗
		65.00	✓
		150.00	100
		<u>\$1,481.00</u>	

L/S \$800 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tan Min 97445749 / 674/8434
 'WP' 16/10/20 @ 3pm.
 Lumpsum 3 days - 4 days
 Resurvey after repair
 Tan Min @ Khant. Co.

Yours Faithfully,
 Southern Motor