

ASS. REC. BY:

Tanglin

REF:

CS/MSG 2011 24/71943

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMY60172

Yr Regn:

01 Sep 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Maserati Ghibli

c.c

2987

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

72977

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

7AMT5576001237715

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/10/20

Survey held at

Perpendicular

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / L.B.I. (\$

### Repair Estimate Quotation

Car Plate	SMU6017Z
Car Make	Maserati
Car Model	Ghibli 3.0
Date of Quote	16 October 2020

#### Silencers

S/N	Parts Description	Price	
1	Rear RH Muffler	\$5,163.00	R✓
2	Flexible Pad	\$47.50	✓
3	RH Rear Silencer Support	\$93.35	de ✓
4	RH Rear Silencer Support Screws	\$11.15	x
5	Spacer	\$52.45	✓
6	Spacer Screws	\$7.40	✓

#### Adblue System

S/N	Parts Description	Price	
1	Adblue Tank	\$5,741.20	✓
2	LH Silencer Heat Shield	\$75.60	✓
3	Rear Nox Sensor	\$2,007.35	✓
4	Collar	\$27.50	✓
5	Adblue Doser Module	\$574.15	✓
6	Adblue Delivery Pipe	\$603.05	✓
7	Exhaust Gas Temperature Sensor	\$355.21	✓
8	Adblue Heater Control Unit	\$479.15	✓
9	Bracket	\$16.50	✓
10	Shield	\$78.10	✓
11	Front Nox Sensor	\$2,544.30	✓
12	Bracket	\$47.50	✓
13	Screw	\$11.15	✓
14	Screw (M6X16)	\$3.75	✓
15	Screw	\$11.15	✓
16	Nut	\$11.15	✓
18	L.H. Strap	\$51.25	✓
19	R.H. Strap	\$47.50	✓
20	Pad	\$262.70	✓
21	Plug	\$213.55	✓
22	Filter	\$29.35	✓
23	Rivet	\$14.90	✓
24	Clip	\$11.15	✓

#### Rear Chassis

S/N	Parts Description	Price	
1	Rear Chassis Assembly	\$4,584.70	✓
2	Screw (M14x145)	\$62.40	✓
3	Screw	\$80.55	✓
4	Clip	\$37.20	✓
5	Clip	\$5.60	✓
6	LH Bracket	\$20.25	✓
7	RH Bracket	\$20.25	✓
8	Screw (M10x21.5)	\$22.30	✓
9	Screw	\$22.30	✓

### Taillight Clusters

S/N	Parts Description	Price
1	RH Taillight Fixed Side	\$1,094.55
2	LH Taillight Fixed Side	\$1,094.55
3	Supplementary Stop Light	\$226.35
4	RH Taillight Mobile Side	\$912.80
5	LH Taillight Mobile Side	\$912.80
6	Rubber	\$7.40
7	Screw (M6x21)	\$27.90
8	LH Reflector	\$84.30
9	RH Reflector	\$84.30
10	R.H. Cap For Screw	\$16.50
11	L.H. Cap For Screw	\$16.50
12	Bushing	\$11.15
13	Screw (M6x16)	\$14.87
14	Rivet	\$14.90

### Bodywork And Rear Outer Trim Panels

S/N	Parts Description	Price
1	LH Body Side Frame Assembly	\$1,643.90
2	RH Body Side Frame Assembly	\$1,643.90
3	Upper LH Headlight Housing Guide	\$164.40
4	Upper RH Headlight Housing Guide	\$165.65
5	Lower LH Headlight Housing Guide	\$140.40
6	Lower RH Headlight Housing Guide	\$140.40
7	Rear Window Cross Member	\$194.95
8	Rear Reinforcement	\$1,090.40
9	Lower Rear Guard Assembly	\$1,090.40
10	Rear Cross Member Assembly	\$570.00
11	LH Rear Side Lower Cover Assembly	\$178.05
12	RH Rear Side Lower Cover Assembly	\$178.05

### Rear Bumper

S/N	Parts Description	Price
1	Rear Bumper	\$2,916.10
2	Rear Bumper Shock Absorber	\$140.85
3	Under Taillight RH Bracket	\$45.85
4	Upper Central Bracket	\$122.30
5	Under-Taillight LH Bracket	\$45.85
6	Gasket	\$22.30
7	RH Bumper Mounting Bracket	\$78.50
8	LH Bumper Mounting Bracket	\$78.50
9	Screw	\$22.30
10	Screw (10x16)	\$7.45
11	Left Rear Bumper Lower Trim	\$532.85
12	Fastener Button	\$15.90
13	Central Lower Trim	\$553.46
14	Right Rear Bumper Lower Trim	\$532.80
15	Screw (10x16)	\$14.90
16	Screw (10x16)	\$7.45
17	Rivet	\$55.80
18	Rivet	\$14.90

**Parking Sensors**

S/N	Parts Description	Price
1	Parking Sensor	\$1,485.30
2	Rear Bumper Parking Sensor Bridle	\$137.55
3	Rear Bumper Parking Sensor Bridle	\$254.45
4	Ring	\$58.65
5	External LH Parking Sensor Sleeve	\$95.00
6	External RH Parking Sensor Sleeve	\$95.00
7	Internal LH Parking Sensor Sleeve	\$95.00
8	Internal RH Parking Sensor Sleeve	\$95.00
9	Clip	\$279.00

**Shields, Trims and Covering Panels**

S/N	Parts Description	Price
1	Screw (M6x16)	\$3.75
2	Light Bar Without Rear Parking Camera	\$627.33
3	Microswitch Replacement Kit	\$304.85
4	Fastener Button	\$122.30

**Trims, Brands and Symbols**

S/N	Parts Description	Price
1	Maserati Logo Emblem	\$142.45
2	Logo On Boot Lid	\$142.45

**Rear Lid**

S/N	Parts Description	Price
1	Fastener Button	\$3.80
2	Boot Lid	\$3,271.25
3	Rear Left Boot Lid Hinge	\$323.00
4	Rear Right Boot Lid Hinge	\$323.00
5	LH Hinge Cover	\$46.30
6	RH Hinge Cover	\$46.30
7	Screw	\$44.65
8	Boot Lid Spring	\$111.55
9	Gasket	\$368.45
10	Boot Lid Cover	\$390.35
11	Antivibrating Pad	\$14.90
12	Nut	\$15.20
13	Fastener Button (6.5x18)	\$169.15
14	Block	\$47.50
15	Pad	\$73.11
16	Rubber Damper	\$1.90
17	Rivet	\$22.30
18	Side Plug	\$3.80
19	Plug	\$5.60
20	LH Door	\$46.30
21	RH Door	\$46.30
22	Liftgate Opening Sensor	\$665.00
23	Screw	\$22.30
24	Rear Bonnet Opening Sensor Cable	\$43.40
25	Screw	\$33.50
26	Clip	\$9.30
27	Rear Bonnet Complete Actuator	\$1,152.40



28	Control Panel Real Bonnet CL	\$123.50
29	Ball Pin	\$5.60
30	Ball Pin	\$5.60
31	Ball Pin	\$18.40
32	LH Bracket	\$78.50
33	Rear Bracket	\$73.15
34	Trim Plate	\$17.80

#### Rear Lid Opening Control

S/N	Parts Description	Price
1	Luggage Compartment Lock	\$147.10
2	Boot Lid Striker	\$27.50
3	Screw	\$33.10
4	Screw	\$33.10

#### Labour To Remove and Replace Parts

S/N	Parts Description	Price
1	Silencer	\$50.00
2	Adblue System	\$350.00
3	Rear Chassis	\$800.00
4	Bodywork and Rear Outer Trim Panels	\$350.00
5	Rear Bumper and Parking Sensor	\$120.00
6	Rear Lid	\$80.00

#### Ad Hoc Labour

S/N	Parts Description	Price
1	<i>Bodywork</i> Chassis Alignment	\$2,000.00
2	Body Paintwork	\$2,000.00
3	Programming and Diagnosis	\$800.00

#### Loss of Use / Rental

S/N	Parts Description	Price
1	14 days @ \$285 per day	\$3,990.00

Shipping Cost and Tax:		TBC
Total Sum:		\$62,717.08

*To 1 Sponge de -*

*End Panel inner garnish de -*

*Taufhi 97495749*

*'WP' 15/10/20*

*Lumpsum*

*Recovery after repair*

*7 days - 8 days*

*taufhi @ kharto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: