

C

1074

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z**AAD2010-047***Not Authenik**11 Pmp & 7550/h Max*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 OCT 2020**SHD9945Z**

VF1ABL15AUC277909

RENAULT

LATITUDE

11/10/2020

CHINA

05/06/2014

PART		LIST	
1	BUMPER COVER FRT	\$ <i>By/CM</i>	747.20 ✓
1	BUMPER BEAM FRT	\$ <i>R</i>	663.70 ✓
1	BUMPER SPOILER FRT	\$ <i>Diy</i>	344.70 ✓
1	BUMPER ABSORBER FRT	\$ <i>CM</i>	394.68 ✓
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$ <i>CM</i>	116.47 ✓
1	BUMPER BRACKET FRT RH (Headlamp Lower)	\$ <i>Ln</i>	116.47 X
1	BUMPER RETAINER FRT LH	\$ <i>CM</i>	101.40 ✓
1	BUMPER RETAINER FRT RH	\$ <i>Ln</i>	101.40 X
1	BUMPER SUPPORT FRT	\$ <i>Ln</i>	10.70 X
1	BUMPER GRILLE LOWER FRT	\$ <i>Ln</i>	147.00 X
1	BUMPER FOG LAMP GRILLE LH	\$ <i>CM</i>	207.21 ✓
1	BUMPER FOG LAMP GRILLE RH	\$ <i>Ln</i>	207.21 X
1	BONNET LOCK	\$ <i>R</i>	152.80 X
1	BONNET HINGE LH	\$ <i>R</i>	237.40 X
1	BONNET HINGE RH	\$ <i>R</i>	237.40 X
1	HEADLAMP LH	\$ <i>Bo</i>	743.60 ✓
1	HEADLAMP RH	\$ <i>mg CM</i>	743.60 ✓
1	HEADLAMP PANEL FRT LH	\$ <i>R</i>	128.30 X
1	HEADLAMP PANEL FRT RH	\$ <i>R</i>	128.30 X
1	RADIATOR GRILLE FRAME	\$ <i>CM</i>	686.00 ✓
1	FRAME FULL SUPPORT PANEL	\$ <i>CM</i>	592.70 ✓
1	FRAME FULL SUPPORT BRACKET	\$ <i>R</i>	41.60 X
1	RADIATOR GRILLE	\$ <i>mg CM</i>	969.90 ✓
1	RADIATOR GRILLE BADGE "RENAULT"	\$ <i>Ln</i>	225.36 ✓
1	DOOR MIRROR ASSY LH	\$ <i>n.c (\$CM)</i>	1,483.40 X
1	FENDER PANEL FRT LH	\$ <i>R</i>	437.10 ✓
1	FENDER PANEL FRT RH	\$ <i>R</i>	437.10 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z**AAD2010-047***Not Authored**11 Pmp & 7550/h Max*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 OCT 2020**SHD9945Z**

VF1ABL15AUC277909

RENAULT

LATITUDE

11/10/2020

CHINA

05/06/2014

PART		LIST	
1	BUMPER COVER FRT	\$ <i>By/CM</i>	747.20 ✓
1	BUMPER BEAM FRT	\$ <i>R</i>	663.70 ✓
1	BUMPER SPOILER FRT	\$ <i>Dir</i>	344.70 ✓
1	BUMPER ABSORBER FRT	\$ <i>CM</i>	394.68 ✓
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$ <i>CM</i>	116.47 ✓
1	BUMPER BRACKET FRT RH (Headlamp Lower)	\$ <i>Ln</i>	116.47 X
1	BUMPER RETAINER FRT LH	\$ <i>CM</i>	101.40 ✓
1	BUMPER RETAINER FRT RH	\$ <i>Ln</i>	101.40 X
1	BUMPER SUPPORT FRT	\$ <i>Ln</i>	10.70 X
1	BUMPER GRILLE LOWER FRT	\$ <i>Ln</i>	147.00 X
1	BUMPER FOG LAMP GRILLE LH	\$ <i>CM</i>	207.21 ✓
1	BUMPER FOG LAMP GRILLE RH	\$ <i>Ln</i>	207.21 X
1	BONNET LOCK	\$ <i>R</i>	152.80 X
1	BONNET HINGE LH	\$ <i>R</i>	237.40 X
1	BONNET HINGE RH	\$ <i>R</i>	237.40 X
1	HEADLAMP LH	\$ <i>Bo</i>	743.60 ✓
1	HEADLAMP RH	\$ <i>mg CM</i>	743.60 ✓
1	HEADLAMP PANEL FRT LH	\$ <i>R</i>	128.30 X
1	HEADLAMP PANEL FRT RH	\$ <i>R</i>	128.30 X
1	RADIATOR GRILLE FRAME	\$ <i>CM</i>	686.00 ✓
1	FRAME FULL SUPPORT PANEL	\$ <i>CM</i>	592.70 ✓
1	FRAME FULL SUPPORT BRACKET	\$ <i>R</i>	41.60 X
1	RADIATOR GRILLE	\$ <i>mg CM</i>	969.90 ✓
1	RADIATOR GRILLE BADGE "RENAULT"	\$ <i>Ln</i>	225.36 ✓
1	DOOR MIRROR ASSY LH	\$ <i>n.c. (\$CM)</i>	1,483.40 X
1	FENDER PANEL FRT LH	\$ <i>R</i>	437.10 ✓
1	FENDER PANEL FRT RH	\$ <i>R</i>	437.10 X

Trans-cab Auto Services Pte Ltd**AAD2010-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,800.00 *500/*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *20/*

To rust-proofing and apply undercoat of the affected areas.

\$ 250.00 *30/*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To remove and refit battery, electrical wiring, fuse box and relay to enable repair.

\$ *nn* 450.00 X

Putty and spray painting of the affected portion.

\$ 1,800.00 *660/***TOTAL \$ 5,620.00****Over All Total \$ 20,840.50****Repair Days (LUMP SUM)****~~20~~ DAYS***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2010-047

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Company

878K

Vehicle to be Exported:

SHD9945Z

Intended Deregistration Date:

Yes

Vehicle Make:

12 Oct 2020

Vehicle Model:

RENAULT

Primary Colour:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Manufacturing Year:

Red

Engine No.:

2014

Chassis No.:

M9R8839C001179

Maximum Power Output:

VF1ABL15AUC277909

Open Market Value:

127.0 kW (170 bhp)

Original Registration Date:

\$19,998.00

First Registration Date:

05 Jun 2014

Transfer Count:

05 Jun 2014

Actual ARF Paid:

0

\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

04 Jun 2022

PARF Rebate Amount:

\$8,123.00

Intended COE Rebate Details

COE Expiry Date:

04 Jun 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$57,338.00

COE Rebate Amount:

\$11,793.00

Total Rebate Amount:

\$19,916.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Oct 2020

OK

8778.93

1406

10185.93

8150