

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z**AAD2010-047***Not Authenik**11 Pmp & 7550/h Max*

Vehicle No.:

Chassis No.:

13 OCT 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9945Z

VF1ABL15AUC277909

RENAULT

LATITUDE

11/10/2020

CHINA

05/06/2014

PART**LIST**

1	BUMPER COVER FRT	\$	<i>By CM</i>	747.20	✓
1	BUMPER BEAM FRT	\$	<i>R</i>	663.70	✓
1	BUMPER SPOILER FRT	\$	<i>Dir</i>	344.70	✓
1	BUMPER ABSORBER FRT	\$	<i>CM</i>	394.68	✓
1	BUMPER BRACKET FRT LH (Headlamp Lower)	\$	<i>CM</i>	116.47	✓
1	BUMPER BRACKET FRT RH (Headlamp Lower)	\$	<i>Ln</i>	116.47	X
1	BUMPER RETAINER FRT LH	\$	<i>CM</i>	101.40	✓
1	BUMPER RETAINER FRT RH	\$	<i>Ln</i>	101.40	X
1	BUMPER SUPPORT FRT	\$	<i>Ln</i>	10.70	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Ln</i>	147.00	X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i>	207.21	✓
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Ln</i>	207.21	X
1	BONNET LOCK	\$	<i>R</i>	152.80	X
1	BONNET HINGE LH	\$	<i>R</i>	237.40	X
1	BONNET HINGE RH	\$	<i>R</i>	237.40	X
1	HEADLAMP LH	\$	<i>Bo</i>	743.60	✓
1	HEADLAMP RH	\$	<i>mg CM</i>	743.60	✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	128.30	X
1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	128.30	X
1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	686.00	✓
1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	41.60	X
1	RADIATOR GRILLE	\$	<i>mg CM</i>	969.90	✓
1	RADIATOR GRILLE BADGE "RENAULT"	\$	<i>Ln</i>	225.36	✓
1	DOOR MIRROR ASSY LH	\$	<i>N.C. (CM)</i>	1,483.40	X
1	FENDER PANEL FRT LH	\$	<i>R</i>	437.10	✓
1	FENDER PANEL FRT RH	\$	<i>R</i>	437.10	X

Trans-cab Auto Services Pte Ltd**AAD2010-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z

1	WHEELARCH FRT LH	\$	CM	191.40	✓
1	BUMPER UNDERTRAY FRT	\$	CM	292.50	✓
1	SUBFRAME OUTER FRT	\$	Sh	1,094.20	X
1	AIR CLEANER BOX	\$	Sh	464.20	✓
1	AIR CLEANER HOSE	\$	Sh	175.85	X
1	AIR CLEANER LOWER	\$	CM	271.26	✓
1	STEERING PUMP ELECTRIC	\$	Di / CM	2,026.70	✓
1	AUTO COMPUTER	\$	Sh	1,287.30	X
1	SUBFRAME OUTER FRT	\$	Sh	1,094.20	X

TOTAL \$ 16,206.11**10% \$ 1,620.61****\$ 14,585.50****Special Nett**

1SET	BUMPER CLIP FRT	\$	na	90.00	665m
1	BUMPER BRACKET CLIP FRT	\$	na	75.00	X
1	BUMPER SUPPORT CLIP FRT	\$	na	10.00	X
1SET	RADIATOR GRILLE SCREW	\$	na	55.00	X
1SET	RADIATOR GRILLE FRAME CLIP L70Y	\$	na	60.00	X
1SET	BUMPER RETAINER CLIP FRT	\$	na	70.00	X
1SET	BUMPER GRILLE LOWER CLIP	\$	na	70.00	X
1	BUMPER FOG LAMP GRILLE CLIP	\$	na	65.00	X
1	BUMPER SPOILER CLIP	\$	na	60.00	X
1SET	WHEELARCH CLIP FRT	\$	na	80.00	✓
1	LICENCE PLATE HOLDER	\$	Sh	80.00	X
1	TOWING FEE	\$		170.00	501

TOTAL \$ 635.00**TOTAL PARTS \$ 15,220.50****LABOUR**

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2010-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9945Z

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,800.00 *5001*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To rust-proofing and apply undercoat of the affected areas.

\$ 250.00 *301*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To remove and refit battery, electrical wiring, fuse box and relay to enable repair.

\$ *nn* 450.00 X

Putty and spray painting of the affected portion.

\$ 1,800.00 *6601***TOTAL \$ 5,620.00****Over All Total \$ 20,840.50****Repair Days (LUMP SUM)****~~20~~ DAYS***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: