

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011101/KGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100482717
Claimant Vehicle No :	GBA4670K	Insured Vehicle No :	SJD297X
Date of Loss:	10/10/2020	Nature of Claim:	TP
		Claim No:	1374228115SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA4670K	Engine No:	1KD1647909
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Chassis No:	JTFAT35Y603001039
Reg. Date:	17/07/2007 (Man. Year: 2007)	Odometer:	389261 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	GREEN-MAX 9 mm	Rear Left Side:	Wanli 1/1 mm
Front Right Side:	GREEN-MAX 9 mm	Rear Right Side:	Wanli 1/1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,641.25	1,792.80	4,848.45	73.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,265.00	1,275.00	50.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,181.25	3,057.80	6,123.45	66.70
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	9,181.25	2,450.00	6,731.25	73.32
+ GST 7.00/7.00% (S\$)	642.69	171.50	471.19	73.32
Nett Amount (S\$)	9,823.94	2,621.50	7,202.44	73.32
+ Car Rental (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		2,861.50		
Global Sum Settlement (S\$)		2,850.00		

INSPECTION

Date of Assignment:	14/10/2020	Yee Auto Pte Ltd (HQ)
Date Inspected:	20/10/2020 Inspected At:	160 SIN MING DRIVE #02-17 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TYRE -RH	Serviceable	180.00 F	*- F
2	1		*REAR AXLE	Serviceable	1,850.90 F	*- FL
3	1		*REAR WHEEL BEARING -RH	Necessary	285.10 F	*285.10 FL
4	1		*REAR WHEEL PANEL MUDFLAP -RH	Distorted	120.00 F	*120.00 FL
5	1		*REAR CARGO ALUMINIUM SIDE GATE -RH	Repair	430.00 F	*- FL
6	1		*REAR CARGO SIDEGATE -RH	Repair	820.00 F	*- FL
7	1		*REAR SIDEGATE PILLAR SAFETY HINGE -RH	Distorted	120.00 F	*120.00 FL
8	1		*REAR STOPPER BRACKET -RH	Bent	70.00 F	*70.00 FL
9	1		*REAR WHEEL PANEL (FRONT)	Repair	280.00 F	*- FL
10	1		*REAR WHEEL PANEL (REAR)	Bent	280.00 F	*232.00 FL
11	1		*REAR CARGO SAFETY BRACKET	Bent	280.00 F	*280.00 FL
12	1		*REAR TAILLAMP PANEL -RH	Repair	185.00 F	*- FL
13	1		*REAR TAILLAMP -RH	Repair	225.00 F	*- FL
14	1		*REAR STOPPERS RUBBER -RH	Missing	60.00 F	*60.00 FL
15	1		*REAR CARGO SIDE PANEL -RH	Bent	485.00 F	*418.00 FL
16	1		*BRAKE OIL	Not Necessary	40.00 F	*- FL
17	1		*REAR AXLE SHAFT -RH	Bent	930.25 F	*805.30 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					6,641.25	2,390.40
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	597.60
Total Parts (\$\$)					6,641.25	1,792.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,000.00	600.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,000.00	500.00
3	TO APPLY RUST -PROOFING ON REPAIRED ,REPLACED PANEL	New	120.00	30.00
4	TO REMOVE /REFIT REAR AXLE & REPLACE	New	250.00	60.00
5	TO CHECK WIRING FUNCTIONS	New	50.00	15.00
6	WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			2,540.00	1,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >