

ASS. REC. BY:

REF:

AIG/ 20011101/K6

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP 24 HRS

07/02

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

/ EST NOT ready

19/11 L1 Imp @ 2450l

Veh No: _____

GPA 4670K

Yr Regn: _____

07 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: _____

Toy Dyna

c.c

2882

Colour: _____

Silver

A/C: Insured / Std / NI / NA

Sp. Reading: _____

389261

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JT FAT 354803001039

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIT / S/Rim / STD A/Rim or

Tyre Size: _____

Green Max 195R15x8
R: Wanli 155R12x8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

10/10/20

D.O.I. _____

20/10/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 6459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 10/10/2020

TP Veh Reg No: SJD297K

Estimate No: ES2000094

Date: 20 Oct 2020

Policy No:

Veh Reg No: GBA4670K

Make/Model: TOYOTA DYNA 150
MANUAL

Chassis No: JTFAT35Y603001039

Engine No: 1KD1647909

Reg. Date: 17/07/2007

Estimate Repair Cost to Vehicle No :GBA4670K

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR TYRE - RH	180.00	1 PC	180.00 X	180.00
Spare Parts				
2 REAR AXLE	1,850.90	1 PC	1,850.90 X	
3 REAR WHEEL BEARING - RH	285.10	1 PC	285.10 ✓	
4 REAR WHEEL PANEL MUDFLAP - RH	120.00	1 PC	120.00 ✓	
5 REAR CARGO ALUMINIUM SIDE GATE - RH	430.00	1 PC	430.00 X	
6 REAR CARGO SIDEGATE - RH	820.00	1 PC	820.00 X	
7 REAR SIDEGATE PILLAR SAFETY HINGE - RH	120.00	1 PC	120.00 ✓	
8 REAR STOPPER BRACKET - RH	70.00	1 PC	70.00 ✓	
9 REAR WHEEL PANEL (FRONT)	280.00	1 PC	280.00 X	
10 REAR WHEEL PANEL (REAR) 232.00	280.00	1 PC	280.00 ✓	
11 REAR CARGO SAFETY BRAKE 618.00	280.00	1 PC	280.00 ✓	
12 REAR TAILLAMP PANEL - RH	185.00	1 PC	185.00 X	
13 REAR TAILLAMP - RH	225.00	1 PC	225.00 X	
14 REAR STOPPER RUBBER - RH	60.00	1 PC	60.00 ✓	
15 REAR CARGO SIDE PANEL - RH 418	485.00	1 PC	485.00 ✓	
16 BRAKE OIL 258	40.00	1 PC	40.00 X	
			5,531.00	5,531.00
Labour				
17 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00 600	
18 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00 500	
19 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00 30	
20 TO REMOVE/REFIT REAR AXLE & REPLACE.	250.00	1 JOB	250.00 80	
21 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00 15	
22 WHEEL ALIGNMENT	120.00	1 T	120.00 60	
			2,540.00	2,540.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/10/2020
TP Veh Reg No: SJD297K

Estimate No: **ES2000094**
Date: 20 Oct 2020
Policy No:
Veh Reg No: **GBA4670K**
Make/Model: TOYOTA DYNA 150
MANUAL
Chassis No: JTFAT35Y603001039
Engine No: 1KD1647909
Reg. Date: 17/07/2007

Estimate Repair Cost to Vehicle No :GBA4670K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 8,251.00
			Add GST @ 7%	577.57
			Total Amount Payable	S\$ 8,828.57

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED TWENTY EIGHT AND CENTS FIFTY SEVEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/10/2020
TP Veh Reg No: SJD297K

Estimate No: ES2000094
Date: 21 Oct 2020
Policy No:
Veh Reg No: GBA4670K
Make/Model: TOYOTA DYNA 150
MANUAL
Chassis No: JTFAT35Y603001039
Engine No: 1KD1647909
Reg. Date: 17/07/2007

Estimate Repair Cost to Vehicle No :GBA4670K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Spare Parts				
1 REAR AXLE SHAFT - RH	805.30	930.25	1 PC	930.25 ✓
			930.25	930.25
Total				S\$ 930.25
GST Amount				S\$ 65.12
Total Amount Payable				S\$ 995.37

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE



Toyota : Dyna : KDY/LY(220,230,250,260) Independent Front Suspension Models : 2006.9- : KDY231(L/R)-TBMGYW3
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°49'	-0°49'	-0°15' 1°15'
3°06'	3°06'	1°15' 2°45'
-0°10'	-0°10'	0°07' 0°12'
13°14'	13°14'	
12°25'	12°25'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°29'	0°29'	-0°15' 1°15'
3°08'	3°08'	1°15' 2°45'
-0°07'	-0°07'	0°07' 0°12'
11°45'	11°45'	
12°14'	12°14'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-1°18'	-1°18'	-0°30' 0°30'
-0°02'	-0°02'	-0°30' 0°30'
1°29'	1°29'	-0°30' 0°30'
-0°17'	-0°17'	0°14' 0°24'

Rear : Left

Actual	Before	Specified Range
-0°19'	-0°20'	
0°24'	0°24'	

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°40'	-2°39'	
-0°55'	-0°55'	

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
2°20'	2°19'	
-0°31'	-0°30'	
0°40'	0°40'	