

ORTDELGRO ENGINEERING PTE LTD AIR ESTIMATE*

VEHICLE NO : SHC8926R
MAKE : HYUNDAI
MODEL : I40

DATE: 13. Oct. 2020
MVA: LOKE WY
DOA: 13. Oct. 2020

Qty	Parts Description/ Labour	Type	Unit Price	NTUC Amount
1	Rear Bumper ✓ <i>OK</i>			\$1,106.00
10	Rear Bumper Clips ✓ <i>MC</i>		\$2.20	\$22.00
1	Rear Bumper Side Bracket - RH X <i>MM</i>			\$35.60
1	Rear Bumper Reinforcement 1 X <i>MM</i>			\$428.40
1	Rear Bumper Reinforcement Bracket RH X <i>MM</i>			\$80.30
1	Rear Bumper Undercover ✓ <i>CUT</i>			\$228.00
1	Rear Bumper Reflector - RH X <i>MM</i>			\$32.00
SUB TOTAL				\$1,932.30
LESS 20%				\$386.46
DISCOUNTED TOTAL				\$1,545.84
1	Rear Bumper Rubber Mat ✓ <i>MC</i>			\$50.00
1	Rear Bumper Reverse Sensor ✓ <i>SLD</i>			\$135.70
				Nett
				Nett
				\$185.70
Labour Charge				
1	Panel Beating			280 \$400.00
1	Spray Painting Charge			200 \$300.00
1	Wiring Charge			30 \$50.00
1	Remove/refix Reverse Sensor			30 \$100.00
1	Towing Fee			\$600.00
TOTAL LABOUR				\$850.00
ESTIMATE TOTAL				\$2,581.54
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK) W MC
13/10/20, 4.00pm
2 days
L/S

L/S = ~~1496.40~~ 1448.50
= ~~1500~~ 1450

My M Sky

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: