

PORTDELGRO ENGINEERING PTE LTD AIR ESTIMATE*

VEHICLE NO : SHC8926R
MAKE : HYUNDAI
MODEL : i40

DATE: 13. Oct. 2020
MVA: LOKE WY
DOA: 13. Oct. 2020

NTUC

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|--|------|------------|--------------|
| 1 | Rear Bumper ✓ <i>OK</i> | | | \$1,106.00 |
| 10 | Rear Bumper Clips ✓ <i>MC</i> | | \$2.20 | \$22.00 |
| 1 | Rear Bumper Side Bracket - RH X <i>MM</i> | | | \$35.60 |
| 1 | Rear Bumper Reinforcement 1 X <i>MM</i> | | | \$428.40 |
| 1 | Rear Bumper Reinforcement Bracket RH X <i>MM</i> | | | \$80.30 |
| 1 | Rear Bumper Undercover ✓ <i>CUT</i> | | | \$228.00 |
| 1 | Rear Bumper Reflector - RH X <i>MM</i> | | | \$32.00 |
| SUB TOTAL | | | | \$1,932.30 |
| LESS 20% | | | | \$386.46 |
| DISCOUNTED TOTAL | | | | \$1,545.84 |
| | | | | |
| 1 | Rear Bumper Rubber Mat ✓ <i>MC</i> | | | \$50.00 |
| 1 | Rear Bumper Reverse Sensor ✓ <i>shd</i> | | | \$135.70 |
| | | | | Nett |
| | | | | Nett |
| | | | | \$185.70 |
| Labour Charge | | | | |
| 1 | Panel Beating | | | 280 \$400.00 |
| 1 | Spray Painting Charge | | | 200 \$300.00 |
| 1 | Wiring Charge | | | 30 \$50.00 |
| 1 | Remove/refix Reverse Sensor | | | 30 \$100.00 |
| 1 | Towing Fee | | | \$600.00 |
| TOTAL LABOUR | | | | \$850.00 |
| ESTIMATE TOTAL | | | | \$2,581.54 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |

Steve (LKK) ML MC
13/10/20, 4.49pm
2 days
L/S
My M shg

L/S = 1496.40
= 1500

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: