

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0773/2020/NS
DATE	:	14-Oct-20
WIP	:	53147

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR TANG SOO TECK
ADDRESS	:	12 SIMEI RISE
		#08-35
		SINGAPORE 528805
TELEPHONE	:	HP +65 86877588
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1700025408-03
VEHICLE NO	:	SLQ 4048 E
MODEL CODE	:	AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR	:	8/7/2017
ENGINE NO	:	CHZ 383462
CHASSIS NO	:	WAUZZZ8V9H1078670
MILEAGE	:	68638KM
DATE IN	:	14-Oct-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	13-Oct-20
PLACE OF ACCIDENT	:	12 SIMEI RISE B1


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 4048 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1500 ✓
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$ 3,000.00	1650 ✓
SUB TOTAL LABOUR CHARGES		: \$ 6,510.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 4048 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓ ✓
6	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	SSD ✓
7	TO RESPRAY REAR BUMPER.	\$ 900.00	SSD ✓
8	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	✗
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ <u>9,212.00</u>	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 4048 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Deformed</i>	\$	1,987.00	✓ 1589.60
2 FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	185.00	+
3 FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>	\$	38.00	+
4 FRONT BUMPER GRILLE - CENTRE <i>cracked</i>	\$	159.00	✓ 126.80
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>	\$	530.00	+
6 FRONT BUMPER CLOSING ELEMENT - LH / RH <i>2H Deformed</i>	2 \$	586.00	? 234.40
7 FRONT BUMPER COVER TRIM - LH <i>Neu</i>	\$	161.00	? X
8 RADIATOR GRILLE <i>cracked</i>	\$	1,406.00	✓ 1124.80
9 RADIATOR GRILLE CLOSING ELEMENT <i>cracked</i>	\$	189.00	? 150.80
10 FRONT BUMPER AIR GUIDE GRILLE - LH <i>ut</i>	\$	186.00	✓ 148.40
11 FRONT REINFORCEMENT BEAM <i>Bent</i>	\$	715.00	? 571.60
12 FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	\$	187.00	? 149.60
13 FOAM FILLER PIECE COVER <i>cracked</i>	\$	121.00	? 96.40
14 AIRCON STICKER <i>3 Neu</i>	NEC \$	8.00	✓ 5.68
15 CAUTION SIGN STICKER	NEC \$	14.00	✓ 10.80
16 SIGNAL HORN - LH HIGH TONE <i>Neu</i>	\$	197.00	X
17 FRONT FENDER - LH <i>Buckled</i>	\$	841.00	✓ 672.80
18 FRONT FENDER ATTACHMENT PARTS <i>3</i>	\$	71.00	+
19 FRONT FENDER BRACKET - LH <i>Neu</i>	\$	38.00	+
20 FRONT FENDER BRACE <i>Neu</i>	\$	95.00	+
SUB TOTAL SPARE PARTS	:	\$ 7,714.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 4048 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 WHEEL HOUSING LINER - LH	<i>Not</i>	\$ 167.00	<i>+</i>
22 WHEEL HOUSING LINER ATTACHMENT PARTS	<i>Not</i>	\$ 88.00	<i>+</i>
23 BONNET <i>Bent Dented</i>		\$ 3,134.00	<i>2507.20</i>
24 BONNET ATTACHMENT PARTS <i>new</i>		\$ 163.00	<i>+</i>
25 BONNET LID HINGE - LH / RH	2	\$ 122.00	<i>+</i>
26 BONNET SAFETY CATCH		\$ 89.00	<i>+</i>
27 BONNET STRIKER - LH / RH	2	\$ 218.00	<i>+</i>
28 BONNET EDGE PROTECTION <i>new</i>		\$ 28.00	<i>21.84</i>
29 BONNET CATCH HOOK		\$ 63.00	<i>+</i>
30 BONNET LID LOCK	2	\$ 423.00	<i>+</i>
31 BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$ 57.00	<i>+</i>
32 LED HEADLIGHT - LH <i>cut</i>		\$ 5,455.00	<i>4364</i>
33 LIFT CYLINDER - LH <i>Not new</i>		\$ 141.00	<i>? X</i>
34 LIFT CYLINDER HOSE <i>new</i>		\$ 67.00	<i>+</i>
35 RADIATOR AIR GUIDE - LH <i>org</i>		\$ 24.00	<i>19.20</i>
36 RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>		\$ 12.00	<i>+</i>
37 REAR BUMPER <i>Regis</i>		\$ 1,944.00	<i>+</i>
38 REAR BUMPER FIXING PARTS <i>Not new</i>		\$ 191.00	<i>+</i>
39 REAR BUMPER SPOILER <i>cut</i>		\$ 234.00	<i>187.20</i>
40 FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	<i>60</i>
41 SUNDRIES <i>new</i>		\$ 350.00	<i>25.60</i>
TOTAL SPARE PARTS	:	\$ 20,744.00	
TOTAL LABOUR CHARGES	:	\$ 9,212.00	
GRAND TOTAL	:	\$ 29,956.00	<i>34,066</i>

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : Adrian Ling
SURVEYED DATE : 14/10/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 08 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT