



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0773/2020/NS
19-Oct-20
Glory Tan
1 OF 1
SLQ 4048 E
AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>concluded.</i>	\$ 719.00	✓
2	Coolant <i>new</i>	\$ 91.00	✓
Labours			
1	To remove and reinstall aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/n 1200	✓
2	To renew lock carrier and align to position.	\$ 2,100.00	1250.
TOTAL		\$ 4,110.00	

For Premium Automobiles Pte Ltd

Adrian Ling.

19/10/20

86/5

Add 3 days.

Authorised Signature

Car-in 19/10/2020

wp: 53147

Kiam/Hong

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Abh - Adnan

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 4048 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER Deformed	\$	1,987.00	✓
2 FRONT BUMPER FIXING PARTS New	\$	185.00	+
3 FRONT BUMPER GUIDE SECTION - LH New	\$	38.00	+
4 FRONT BUMPER GRILLE - CENTRE Cracked	\$	159.00	✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE New	\$	530.00	+
6 FRONT BUMPER CLOSING ELEMENT LH / RH 2	\$	586.00	293
7 FRONT BUMPER COVER TRIM - LH ?	\$	161.00	
8 RADIATOR GRILLE Cracked	\$	1,406.00	✓
9 RADIATOR GRILLE CLOSING ELEMENT Cracked	\$	189.00	✓
10 FRONT BUMPER AIR GUIDE GRILLE - LH Lt	\$	186.00	✓
11 FRONT REINFORCEMENT BEAM Best	\$	715.00	✓
12 FRONT BUMPER FOAM FILLER PIECE Cracked	\$	187.00	✓
13 FOAM FILLER PIECE COVER Cracked	\$	121.00	✓
14 AIRCON STICKER } New	NEC \$	8.00	✓
15 CAUTION SIGN STICKER } New	NEC \$	14.00	✓
16 SIGNAL HORN - LH HIGH TONE New	\$	197.00	x
17 FRONT FENDER - LH Buckled	\$	841.00	✓
18 FRONT FENDER ATTACHMENT PARTS }	\$	71.00	+
19 FRONT FENDER BRACKET - LH }	\$	38.00	+
20 FRONT FENDER BRACE }	\$	95.00	+
SUB TOTAL SPARE PARTS	:	\$ 7,714.00	

Supp

Lak camer. x1 = 719

colant x4 = \$91



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 4048 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 WHEEL HOUSING LINER - LH	1	\$ 167.00	X
22 WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 88.00	X
23 <u>BONNET</u> <i>Paint Dented</i>	1	\$ 3,134.00	
24 BONNET ATTACHMENT PARTS	1	\$ 163.00	X
25 BONNET LID HINGE - LH / RH	2	\$ 122.00	X
26 BONNET SAFETY CATCH	1	\$ 89.00	X
27 BONNET STRIKER - LH / RH	2	\$ 218.00	X
28 <u>BONNET EDGE PROTECTION</u>	1	\$ 28.00	✓
29 BONNET CATCH HOOK	1	\$ 63.00	X
30 BONNET LID LOCK	2	\$ 423.00	X
31 BONNET BOWDEN CABLE - CENTRE	1	\$ 57.00	X
32 <u>LED HEADLIGHT - LH</u>	1	\$ 5,455.00	✓
33 LIFT CYLINDER - LH	1	\$ 141.00	?
34 LIFT CYLINDER HOSE	1	\$ 67.00	X
35 <u>RADIATOR AIR GUIDE - LH</u>	1	\$ 24.00	✓
36 RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 12.00	X
37 REAR BUMPER	1	\$ 1,944.00	X
38 REAR BUMPER FIXING PARTS	1	\$ 191.00	X
39 <u>REAR BUMPER SPOILER</u>	1	\$ 234.00	✓
40 FRONT NO PLATE	1	\$ 60.00	✓
41 SUNDRIES	1	\$ 350.00	?
TOTAL SPARE PARTS	:	\$ 20,744.00	
TOTAL LABOUR CHARGES	:	\$ 9,212.00	
GRAND TOTAL	:	\$ 29,956.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

N 016 185 7 X 10

Revised
19/10/20 - Adrian
S.S.