

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0773/2020/NS
DATE : 14-Oct-20
WIP : 53147

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

11 days - ok - Jy - 18 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TANG SOO TECK
ADDRESS : 12 SIMEI RISE
#08-35
SINGAPORE 528805
TELEPHONE : HP +65 86877588
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700025408-03
VEHICLE NO : SLQ 4048 E
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 08/07/2017
ENGINE NO : CHZ 383462
CHASSIS NO : WAUZZZ8V9H1078670
MILEAGE : 68638KM
DATE IN : 14-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Oct-20
PLACE OF ACCIDENT : 12 SIMEI RISE B1

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 4048 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,500.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES.	\$	3,000.00	\$	1,650.00
SUB TOTAL LABOUR CHARGES		:	\$ 6,510.00	\$	3,760.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 4048 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,760.00
5	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	\$ 280.00	\$ 280.00
6	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,050.00	\$ 500.00
7	TO RESPRAY REAR BUMPER.		\$ 900.00	\$ 550.00
8	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N	\$ 280.00	
9	SUPPLEMENTARY		\$ 3,300.00	\$ 2,450.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,512.00	\$ 7,732.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 4048 E

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER		\$	1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS		\$	185.00	
3	FRONT BUMPER GUIDE SECTION - LH		\$	38.00	
4	FRONT BUMPER GRILLE - CENTRE		\$	159.00	\$ 126.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	530.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	586.00	\$ 234.40
7	FRONT BUMPER COVER TRIM - LH		\$	161.00	
8	RADIATOR GRILLE		\$	1,406.00	\$ 1,124.80
9	RADIATOR GRILLE CLOSING ELEMENT		\$	189.00	\$ 150.80
10	FRONT BUMPER AIR GUIDE GRILLE - LH		\$	186.00	\$ 148.40
11	FRONT REINFORCEMENT BEAM		\$	715.00	\$ 571.60
12	FRONT BUMPER FOAM FILLER PIECE		\$	187.00	\$ 149.60
13	FOAM FILLER PIECE COVER		\$	121.00	\$ 96.40
14	AIRCON STICKER	NEC	\$	8.00	\$ 5.68
15	CAUTION SIGN STICKER	NEC	\$	14.00	\$ 10.80
16	SIGNAL HORN - LH HIGH TONE		\$	197.00	
17	FRONT FENDER - LH		\$	841.00	\$ 672.80
18	FRONT FENDER ATTACHMENT PARTS		\$	71.00	
19	FRONT FENDER BRACKET - LH		\$	38.00	
20	FRONT FENDER BRACE		\$	95.00	
SUB TOTAL SPARE PARTS		:	\$	7,714.00	\$ 4,881.68

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 4048 E

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
	<i>c/f</i>		\$	4,881.68
21	WHEEL HOUSING LINER - LH		\$ 167.00	
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
23	BONNET		\$ 3,134.00	\$ 2,507.20
24	BONNET ATTACHMENT PARTS		\$ 163.00	
25	BONNET LID HINGE - LH / RH	2	\$ 122.00	
26	BONNET SAFETY CATCH		\$ 89.00	
27	BONNET STRIKER - LH / RH	2	\$ 218.00	
28	BONNET EDGE PROTECTION		\$ 28.00	\$ 21.84
29	BONNET CATCH HOOK		\$ 63.00	
30	BONNET LID LOCK	2	\$ 423.00	
31	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	
32	LED HEADLIGHT - LH		\$ 5,455.00	\$ 4,364.00
33	LIFT CYLINDER - LH		\$ 141.00	
34	LIFT CYLINDER HOSE		\$ 67.00	
35	RADIATOR AIR GUIDE - LH		\$ 24.00	\$ 19.20
36	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 12.00	
37	REAR BUMPER		\$ 1,944.00	
38	REAR BUMPER FIXING PARTS		\$ 191.00	
39	REAR BUMPER SPOILER		\$ 234.00	\$ 187.20
40	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
41	SUPPLEMENTARY		\$ 810.00	\$ 647.52
42	SUNDRIES		\$ 350.00	\$ 25.60
TOTAL SPARE PARTS		:	\$ 21,554.00	\$ 12,714.24
TOTAL LABOUR CHARGES		:	\$ 12,512.00	\$ 7,732.00
GRAND TOTAL		:	\$ 34,066.00	\$ 20,446.24



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0773/2020/NS

19-Oct-20

Glory Tan

1 OF 1

SLQ 4048 E

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier	\$ 719.00	\$ 575.20
2	Coolant	\$ 91.00	\$ 72.32
			<u>\$ 647.52</u>
Labours			
1	To remove and reinstall aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	s/n \$ 1,200.00	\$ 1,200.00
2	To renew lock carrier and align to position.	\$ 2,100.00	\$ 1,250.00
TOTAL		<u>\$ 4,110.00</u>	<u>\$ 3,097.52</u>

For Premium Automobiles Pte Ltd

Authorised Signature

