

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0753/2020/NS  
DATE : 9-Oct-20  
WIP : 52334

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

Dear Adrian,

3 days ok - 27/01/2021 - Carrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT  
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHONG MINGYANG(ZHANG MINGYANG)  
ADDRESS : 31 PUNGGOL FIELD  
#13-06  
SINGAPORE 828816  
TELEPHONE : HP +65 90170157  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800116197-01  
VEHICLE NO : **SME 3816 M**  
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI CO  
MODEL YEAR : 27/9/2018  
ENGINE NO : CZE 693571  
CHASSIS NO : WAUZZZ8VXJ1078294  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 7-Oct-20  
PLACE OF ACCIDENT : NOVENA SQUARE CARPARK LVL 5A

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 3816 M**

| S/N                         | NATURE OF JOBS                                                                                                               |        | ESTIMATED<br>CHARGES |    | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|----|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.   | S/N \$ | 280.00               | \$ | 280.00                        |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.                                                          | S/N \$ | 350.00               | \$ | 250.00                        |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 1,000.00             | \$ | 500.00                        |
| 4                           | TO RESPRAY FRONT BUMPER.                                                                                                     | \$     | 1,100.00             | \$ | 550.00                        |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                               | S/N \$ | 192.00               | \$ | 192.00                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                              | :      | <b>\$ 2,922.00</b>   | \$ | <b>1,772.00</b>               |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 3816 M**

| S/N PARTS DESCRIPTION                         | QTY | DAMAGED PARTS & PRICES |                    |
|-----------------------------------------------|-----|------------------------|--------------------|
|                                               |     | S/NETT                 | REMARKS            |
| 1 FRONT BUMPER                                |     | \$ 1,987.00            | \$ 1,589.60        |
| 2 FRONT BUMPER FIXING PARTS                   |     | \$ 185.00              |                    |
| 3 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE |     | \$ 530.00              |                    |
| 4 FRONT BUMPER GRILLE - CENTRE                |     | \$ 159.00              |                    |
| 5 FRONT BUMPER CLOSING ELEMENT - RH           |     | \$ 293.00              |                    |
| 6 FRONT BUMPER COVER TRIM - RH                |     | \$ 161.00              |                    |
| 7 RADIATOR GRILLE                             |     | \$ 1,406.00            |                    |
| 8 RADIATOR GRILLE CLOSING ELEMENT             |     | \$ 189.00              |                    |
| 9 FRONT BUMPER AIR GUIDE GRILLE - RH          |     | \$ 186.00              | \$ 148.40          |
| 10 AIRCON STICKER                             | NEC | \$ 8.00                |                    |
| 11 CAUTION SIGN STICKER                       | NEC | \$ 14.00               |                    |
| 12 FRONT REINFORCEMENT BEAM                   |     | \$ 715.00              |                    |
| 13 FRONT BUMPER FOAM FILLER PIECE             |     | \$ 187.00              |                    |
| 14 FOAM FILLER PIECE COVER                    |     | \$ 121.00              |                    |
| 15 LED HEADLIGHT - RH                         |     | \$ 5,455.00            | \$ 4,364.00        |
| 16 LIFT CYLINDER - RH                         |     | \$ 141.00              |                    |
| 17 RADIATOR AIR GUIDE - RH                    |     | \$ 24.00               |                    |
| 18 FRONT NO PLATE                             | S/N | \$ 60.00               |                    |
| 19 SUNDRIES                                   |     | \$ 200.00              |                    |
| <b>TOTAL SPARE PARTS</b>                      | :   | <b>\$ 12,021.00</b>    | <b>\$ 6,102.00</b> |
| <b>TOTAL LABOUR CHARGES</b>                   | :   | <b>\$ 2,922.00</b>     | <b>\$ 1,772.00</b> |
| <b>GRAND TOTAL</b>                            | :   | <b>\$ 14,943.00</b>    | <b>\$ 7,874.00</b> |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

bl-27/11/20