

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

CHEN YINGCHAO  
BLK 335B ANCHORVALE CRESCENT #09-92  
SINGAPORE 542335

Contact : 83828180

TP Ching.  
Xiao Chen.

## ESTIMATE

Repair Code : CLM15050

Date in : 14/10/2020

Vehicle Num. : SMS546M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31322556/LEB6742567

### Parts and Labour Assesment

| Description of part                                   | Qty | Unit Price | Amount            |
|-------------------------------------------------------|-----|------------|-------------------|
| EAR TAILGATE 'LOGO' EMBLEM <i>neu</i>                 | 1   | 25.00      | ✓ 25.00           |
| REAR BUMPER <i>Rehd</i>                               | 1   | 762.70     | ✓ 762.70          |
| REAR BUMPER REFLECTOR L/R <i>neu</i>                  | 2   | 141.10     | + 282.20          |
| REAR BUMPER SIDE COVER L/R <i>Rehd</i>                | 2   | 195.00     | ✓ 390.00          |
| REAR BUMPER SIDE RETAINER L/R <i>neu</i>              | 2   | 23.00      | ✓ 46.00           |
| REAR BUMPER UNDER COVER <i>neu</i>                    | 1   | 250.00     | + 250.00          |
| REAR END PANEL <i>Rehd</i>                            | 1   | 415.60     | ✓ 415.60          |
| REAR END PANEL ANTENNA SENSOR <i>could</i>            | 1   | 60.10      | ✓ 60.10           |
| REAR END PANEL BUZZLE SENSOR <i>could</i>             | 1   | 85.20      | ✓ 85.20           |
| REAR END PANEL INNER TOP GARNISH <i>Rehd</i>          | 1   | 98.00      | ✓ 98.00           |
| REAR FENDER INNER TRIM BOARD L/R <i>could</i>         | 2   | 295.00     | ✓ 590.00          |
| REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Rehd</i> | 1   | 485.30     | ✓ 485.30          |
| REAR FLOOR PANEL TOP BOARD COVER <i>Rehd</i>          | 1   | 430.30     | ✓ 430.30          |
| REAR TAILGATE <i>Distal</i>                           | 1   | 953.30     | ✓ 953.30          |
| REAR TAILGATE 'HYBRID' EMBLEM <i>neu</i>              | 1   | 75.80      | ✓ 75.80           |
| REAR TAILGATE 'VEZEL' EMBLEM <i>neu</i>               | 1   | 56.20      | ✓ 56.20           |
| REAR TAILGATE CAMERA <i>could</i>                     | 1   | 1080.00    | 380(SW) ✓ 1080.00 |
| REAR TAILGATE HINGES L/R <i>neu</i>                   | 2   | 50.00      | + 100.00          |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

CHEN YINGCHAO

BLK 335B ANCHORVALE CRESCENT #09-92

SINGAPORE 542335

Contact : 83828180

## ESTIMATE

Repair Code : CLM15050

Date in : 14/10/2020

Vehicle Num. : SMS546M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31322556/LEB6742567

|                                              |                        |   |        |          |        |
|----------------------------------------------|------------------------|---|--------|----------|--------|
| REAR TAILGATE INNER PULL HANDLE              | <i>Neu</i>             | 1 | 27.50  | <i>+</i> | 27.50  |
| REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R | <i>Neu</i>             | 2 | 18.50  | <i>+</i> | 37.00  |
| REAR TAILGATE INNER TRIM BOARD               | <i>Could</i>           | 1 | 153.40 | <i>✓</i> | 153.40 |
| REAR TAILGATE LOCK STRIKER                   | <i>Neu</i>             | 1 | 27.50  | <i>+</i> | 27.50  |
| REAR TAILGATE MECHANISM LOCK                 | <i>Ignored Jammed</i>  | 1 | 180.00 | <i>✓</i> | 180.00 |
| REAR TAILGATE OUTER GARNISH                  | <i>Could</i>           | 1 | 220.00 | <i>✓</i> | 220.00 |
| REAR TAILGATE OUTER LOCK SWITCH              | <i>Neu</i>             | 1 | 138.00 | <i>+</i> | 138.00 |
| REAR TAILGATE REFLECTOR INNER GASKET L/R     | <i>Neu</i>             | 2 | 38.50  | <i>+</i> | 77.00  |
| REAR TAILGATE REFLECTOR L/R                  | <i>LH at, RH could</i> | 2 | 413.20 | <i>✓</i> | 826.40 |
| REAR TAILGATE WEATHER STRIP                  | <i>cut</i>             | 1 | 96.80  | <i>✓</i> | 96.80  |
| REAR TAILGATE WINDSCREEN MOULDING L/R        | <i>Yes</i>             | 2 | 50.00  | <i>✓</i> | 100.00 |
| REAR TAILGATE WINDSCREEN MOULDING T/L        |                        | 2 | 50.00  | <i>✓</i> | 100.00 |
| REAR TAILGATE WIPER MOTOR                    | <i>Demd</i>            | 1 | 290.00 | <i>✓</i> | 290.00 |
| REAR TAILLAMP INNER GASKET L/R               | <i>Neu</i>             | 2 | 38.50  | <i>✓</i> | 77.00  |
| REAR TAILLAMP L/R                            | <i>cut</i>             | 2 | 474.60 | <i>✓</i> | 949.20 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

CHEN YINGCHAO  
BLK 335B ANCHORVALE CRESCENT #09-92  
SINGAPORE 542335

Contact : 83828180

## ESTIMATE

Repair Code : CLM15050

Date in : 14/10/2020

Vehicle Num. : SMS546M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31322556/LEB6742567

|                                                        |                 |                  |
|--------------------------------------------------------|-----------------|------------------|
| Subtotal before discount                               |                 | 9,485.50         |
| Percentage discount 20%                                | 7466.30 S.N:380 | 1,897.10         |
| Sub-total 1                                            |                 | 7,588.40         |
| REAR BUMPER CLIPS - SET <i>nk</i>                      | 1 80.00         | <i>30</i> 80.00  |
| REAR BUMPER REVERSE SENSOR - SET <i>Dan d</i>          | 1 300.00        | <i>20</i> 300.00 |
| REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>nk</i> | 2 40.00         | <i>60</i> 80.00  |
| REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>nk</i>   | 1 50.00         | <i>30</i> 50.00  |
| REAR TAILGATE NUMBER PLATE <i>lt</i>                   | 1 25.00         | <i>✓</i> 25.00   |
| REAR TAILGATE NUMER PLATE HOLDER <i>nk</i>             | 1 50.00         | <i>+</i> 50.00   |
| REAR TAILGATE OUTER GARNISH CLIPS - SET <i>nk</i>      | 1 30.00         | <i>20</i> 30.00  |
| REAR TAILGATE WINDSCREEN SEALANT <i>nk</i>             | 1 80.00         | <i>60</i> 80.00  |
| REAR TAILLAMP CLIPS L/R - SET <i>nk</i>                | 2 25.00         | <i>✓</i> 50.00   |
| Subtotal before discount                               |                 | 745.00           |
| Percentage discount 0%                                 |                 | 0.00             |
| Sub-total 2                                            |                 | 745.00           |
| Parts-total                                            |                 | 8,333.40         |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

*80* 100.00  
*120* 150.00  
*80* 140.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

CHEN YINGCHAO

BLK 335B ANCHORVALE CRESCENT #09-92

SINGAPORE 542335

Contact : 83828180

## ESTIMATE

Repair Code : CLM15050

Date in : 14/10/2020

Vehicle Num. : SMS546M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31322556/LEB6742567

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

8w 1,100.00

8w 1,100.00

2020

60 120.00

80.00

Labour Total

2,790.00

Parts & Labour Total

11,123.40

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 4

Adrian L  
h/s 15/10/20

06 Days -

total: 8848.04

E/S: 71C ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: