



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

FWD/FC(SHD3200D)
DOA: 05/10/2020@1500

MS FIRST CAPITAL INSURANCE PTE LTD

09/10/2020

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SCR 8831 K - TOYOTA WISH 1.8 CVT
CHASSIS NO: JTDGG20W90J003645 (2016)

1 pc	Rear bumper retainer	\$	45.00	XNN
1 pc	Rear bumper	\$	240.00	Rx
		\$	285.00	

Remove necessary parts: jacking, panel beating, repair and
straighten front fender LH inclusive replacing the above.

\$ 200.00 ✓

Putty and respray rear fender LH and rear bumper.

\$ 400.00 300

\$ 885.00

ADD 7% GST

\$ 61.95

\$ 946.95

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 1749549
WP
16/10/20 @ 1230pm
Resurvey after repair
2 days
Tanpin @ 11hant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: