

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0776/2020/NS
DATE : 15-Oct-20
WIP : 53301

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMU 4154 Z

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR MAHMOUD ESMAEILI
ADDRESS : 52 TAMAN NAKHODA
SINGAPORE 257769
TELEPHONE : HP +65 97383034
TYPE OF CLAIM : ~~THIRD PARTY CLAIM~~ OD claim
POLICY NO : 1900004359-01
VEHICLE NO : **SMH 1327 E**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 11/1/2019
ENGINE NO : DAX 149252
CHASSIS NO : WAUZZZF3K2012064
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Oct-20
PLACE OF ACCIDENT : CARPARK REFLEXIONS CLOSE TO
CLUBHOUSE LOBBY 33



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 1327 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00	1600
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS. <i>Door</i>	\$ 3,500.00	2250. $550 \times 3 = 1650$ spoiler = 200 Arch trim $4 \times 2 = 200 \times 2 = 400$
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,152.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Distorted</i>	\$	2,595.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	267.00	✗
3 FRONT BUMPER SECURING STRIP - RH <i>?</i>	\$	37.00	?
4 FRONT BUMPER CLOSING ELEMENT - RH <i>?</i>	\$	111.00	?
5 FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	142.00	+
6 FRONT SPOILER <i>Del'd</i>	\$	754.00	✓
7 FRONT BUMPER UNDERRUN BAR <i>new</i>	\$	474.00	+
8 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	\$	171.00	?
9 RADIATOR GRILLE <i>new</i>	\$	3,490.00	+
10 QUATTRO INSCRIPTION <i>new</i>	\$	95.00	✗
11 RADIATOR GRILLE STRIKER PLATE <i>new</i>	\$	241.00	+
12 FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	\$	574.00	✓
13 FRONT BUMPER END CAP - RH <i>new</i>	\$	91.00	✓
14 FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$	285.00	?
15 FRONT BUMPER CARRIER <i>?</i>	\$	911.00	?
16 FRONT BUMPER TOP COVER <i>new</i>	\$	127.00	+
17 FRONT BUMPER GUIDE SECTION - RH <i>?</i>	\$	38.00	?
18 CAUTION SIGN STICKER <i>new</i>	NEC \$	14.00	+
19 AIRCON STICKER <i>new</i>	NEC \$	20.00	+
20 FRONT PARKING AID SENSOR - OUTER <i>?</i>	\$	242.00	?
SUB TOTAL SPARE PARTS	:	\$	10,679.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	REMARKS
S/NETT			
21 HORN - RH HIGH TONE	1	\$ 193.00	✓
22 FRONT FENDER - RH	1	\$ 1,411.00	✓
23 FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	+
24 FRONT FENDER BRACE - RH	1	\$ 222.00	+
25 FRONT FENDER BRACKET - RH	1	\$ 17.00	+
26 HEADLIGHT TOP COVER - RH	1	\$ 39.00	?
27 WHEEL HOUSING LINER - RH	1	\$ 275.00	+
28 WHEEL SPOILER	1	\$ 153.00	?
29 S-LINE INSCRIPTION	1	\$ 122.00	✓
30 BONNET IMPACT PROTECTION - LH	1	\$ 28.00	+
31 BONNET IMPACT PROTECTION - RH	1	\$ 27.00	+
32 BONNET IMPACT PROTECTION - CENTRE	1	\$ 27.00	+
33 BONNET LID LOCK	1	\$ 212.00	+
34 BONNET STRIKER - RH	1	\$ 119.00	+
35 HEADLIGHT MOUNTING - RH	1	\$ 117.00	?
36 LED HEADLIGHT - RH	1	\$ 7,931.00	✓
37 LIGHT CONTROL SYSTEM CONTROL UNIT	1	\$ 715.00	+
38 MAIN LIGHT ELECTRONICS POWER MODULE - RH	1	\$ 749.00	+
39 LED WITH HEAT SINK - RH	1	\$ 1,086.00	+
40 HEADLIGHT HOSE - RH	1	\$ 38.00	+
SUB TOTAL SPARE PARTS	:	\$ 13,547.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 HEADLAMP REPAIR KIT - RH <i>Not m.</i>		\$ 126.00	X
42 LIFT CYLINDER - RH ?		\$ 138.00	?
43 LIFT CYLINDER HOSE <i>Not m.</i>		\$ 124.00	X
44 RADIATOR AIR GUIDE - RH ?		\$ 58.00	?
45 FRONT WHEEL COVER - LH / RH <i>LH m, RH not</i>	2	\$ 1,250.00	✓
46 FRONT ALUMINIUM RIM - RH <i>Not m.</i>		\$ 1,091.00	X
47 FRONT NO PLATE <i>Not m.</i>	S/N	\$ 60.00	X
48 SUNDRIES ?		\$ 250.00	?
TOTAL SPARE PARTS	:	\$ 27,323.00	
TOTAL LABOUR CHARGES	:	\$ 6,152.00	
GRAND TOTAL	:	\$ 33,475.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lj

SURVEYED DATE

: 16/10/20.

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 05 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT