

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0776/2020/NS
21-Dec-20
GEORGE
1 of 1
SMH 1327 E
Audi Q5 Sport 2.0 TFSI Qu

Quantity	Description	Unit Price	Amount
Labour			
1	To remove and reinstall aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00	✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1250.
Parts			
1	FRONT LOCK CARRIER WITH MOUNTING <i>cracked</i>	\$ 1,384.00	✓
2	RADIATOR COOLANT <i>new</i>	\$ 177.00	✓
GRAND TOTAL		\$ 1,561.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Add 3 days

Car-in

22/12/2020.

wip = 5330 /

kiam/keong



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER Distorted	5	\$	2,595.00	✓
2 FRONT BUMPER FIXING PARTS new	5	\$	267.00	✓
* 3 FRONT BUMPER SECURING STRIP - RH Damaged	5	\$	37.00	✓
4 FRONT BUMPER CLOSING ELEMENT - RH	5	\$	111.00	?
5 FRONT BUMPER GRILLE - CENTRE new	5	\$	142.00	✓
6 FRONT SPOILER Del'd	5	\$	754.00	✓
7 FRONT BUMPER UNDERRUN BAR new	5	\$	474.00	✓
8 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	5	\$	171.00	?
9 RADIATOR GRILLE Not new	5	\$	3,490.00	✓
10 QUATTRO INSCRIPTION new	5	\$	95.00	✓
11 RADIATOR GRILLE STRIKER PLATE new	5	\$	241.00	✓
12 FRONT BUMPER AIR GUIDE GRILLE - RH Missing	5	\$	574.00	✓
13 FRONT BUMPER END CAP - RH Del'd	5	\$	91.00	✓
14 FRONT BUMPER FOAM FILLER PIECE	5	\$	285.00	✓
15 FRONT BUMPER CARRIER	5	\$	911.00	?
16 FRONT BUMPER TOP COVER new	5	\$	127.00	✓
* 17 FRONT BUMPER GUIDE SECTION - RH Del'd	5	\$	38.00	✓
18 CAUTION SIGN STICKER new	NEC	\$	14.00	✓
19 AIRCON STICKER new	NEC	\$	20.00	✓
20 FRONT PARKING AID SENSOR - OUTER ?	5	\$	242.00	✓
SUB TOTAL SPARE PARTS		:	\$	10,679.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 7323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 HORN - RH HIGH TONE <i>crushed</i>	\$	193.00	✓
22 FRONT FENDER - RH <i>crushed Buckled</i>	\$	1,411.00	✓
23 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	66.00	+
24 FRONT FENDER BRACE - RH <i>green</i>	\$	222.00	+
25 FRONT FENDER BRACKET - RH	\$	17.00	+
26 HEADLIGHT TOP COVER - RH	\$	39.00	?
27 WHEEL HOUSING LINER - RH <i>new</i>	\$	275.00	+
28 WHEEL SPOILER	\$	153.00	?
29 S-LINE INSCRIPTION <i>new</i>	\$	122.00	✓
30 BONNET IMPACT PROTECTION - LH <i>green</i>	\$	28.00	+
31 BONNET IMPACT PROTECTION - RH	\$	27.00	+
32 BONNET IMPACT PROTECTION - CENTRE <i>new</i>	\$	27.00	+
33 BONNET LID LOCK <i>green</i>	\$	212.00	+
34 BONNET STRIKER - RH	\$	119.00	+
35 HEADLIGHT MOUNTING - RH <i>crushed</i>	\$	117.00	✓
36 LED HEADLIGHT - RH <i>crushed</i>	\$	7,931.00	✓
37 LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$	715.00	+
38 MAIN LIGHT ELECTRONICS POWER MODULE - RH <i>new</i>	\$	749.00	+
39 LED WITH HEAT SINK - RH <i>new</i>	\$	1,086.00	+
40 HEADLIGHT HOSE - RH <i>new</i>	\$	38.00	+
SUB TOTAL SPARE PARTS	:	\$ 13,547.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1327 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41	HEADLAMP REPAIR KIT - RH <i>Not in</i>		\$ 126.00	X
42	LIFT CYLINDER - RH <i>Not in</i>		\$ 138.00	X
43	LIFT CYLINDER HOSE <i>Not in</i>		\$ 124.00	X
44	RADIATOR AIR GUIDE - RH ?		\$ 58.00	?
45	FRONT WHEEL COVER - LH / RH <i>LH Not in, RH Not in</i>	2	\$ 1,250.00	✓
46	FRONT ALUMINIUM RIM - RH <i>Not in</i>		\$ 1,091.00	X
47	FRONT NO PLATE <i>Not in</i>	S/N	\$ 60.00	X
48	SUNDRIES ?		\$ 250.00	?
TOTAL SPARE PARTS			\$ 27,323.00	
TOTAL LABOUR CHARGES			\$ 6,152.00	
GRAND TOTAL			\$ 33,475.00	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.